

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	J	M	F	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5															
7	3	9						14						15						25						28						30						57		58	
		LICENSEE CODE												LICENSE NUMBER												LICENSE TYPE															

CON'T

7 8

0	1
---	---

REPORT SOURCE

L	(6)	0	5	0	0	0	3	4	8	(7)	0	4	1	3	8	3	(8)	0	5	1	3	8	3	(9)
---	-----	---	---	---	---	---	---	---	---	-----	---	---	---	---	---	---	-----	---	---	---	---	---	---	-----

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | At 0338 on 4/13/83, while decreasing power for a maintenance outage, RCS Tavg
03 | decreased to approximately 540°F due to excessive feedwater flow to the 1A steam
04 | generator. Tech. Spec. 3.1.1.4, in part, requires RCS Tavg to be greater than or
05 | equal to 541°F. Tech. Spec. 3.1.1.4 action statement requirements were met.
06 | Health/safety of the public was not affected. A similar occurrence was reported in
07 | LER 83-014/03L-0.

0 8 1
© 2000 by The U.S. Department of Education. All rights reserved. This document is a U.S. Government work and, as such, is in the public domain in the United States of America.

0 5
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 C R 11 E 12 E 13 V A L V E X 14 F 15 G 16
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 LSP-RO REPORT NUMBER 18 EVENT YEAR 19 20 SEQUENTIAL REPORT NO. 21 OCCURRENCE CODE 22 REPORT TYPE 23 REVISION NO.

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER	
E	(12) Z	(19) Z	(20) Z	(21) Z	0 0 0 0 0	(22) N	(23) N	(24) N	(25) K 0 8 5
33	34	35	36	37	40	41	42	43	44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 10 | This event was due to excessive leakby on the 1A main feedwater regulating bypass
1 11 | valve. RCS Tavg was verified to be greater than or equal to 541°F at 0342 on
1 12 | 4/13/83. The stroke on the 1A main feedwater regulating bypass valve was adjusted
1 13 | and verification of proper valve seating was performed.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
1	5	D	(28)	0	0	NA	(30)	A	(31)	Operational Event	(32)

ACTIVITY CONTENT
RELEASED OF RELEASE

1 5
7 8 9 10 11

Z 33 Z 34

AMOUNT OF ACTIVITY (35)
NA

45 46 47 48 49 50

LOCATION OF RELEASE (36)
NA

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7		0	0	0	37	Z	38	39	NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	5	0	0
2	3	40	NA

1 3 7 17 NA S PDR

PUBLICATION		DESCRIPTION		NRC USE ONLY	
2	0	N	44	NA	

NAME OF PREPARER W. G. Hairston, III

PHONE. (205) 899-5156

978-1-55017-926-6