

NRC FORM 366
(12-81)
10 CFR 50U.S. NUCLEAR REGULATORY COMMISSION
LICENSEE EVENT REPORTAPPROVED BY OMB
3150-0011

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 C A S O S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 3 6 2 7 0 3 0 8 8 3 8 0 8 0 8 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 While in Mode 5, early warning fire detectors in Zone 41 were found inoperable

03 during performance of the 6-month fire detection channel functional test. An

04 hourly firewatch was posted within one hour in accordance with LCO 3.3.3.7

05 Action Statement 'a'. Health and safety of the public were not affected.

06

07

08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
A B 11 E 12 A 13 I N S T R U 14 E 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 6017 LER/NO REPORT NUMBER 8 3 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
18 ACTION TAKEN B 18 Z 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
19 FUTURE ACTION Z 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
20 EFFECT ON PLANT Z 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
21 SHUTDOWN METHOD Z 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
22 HOURS 0 0 0 0 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
23 ATTACHMENT SUBMITTED N 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
24 NPD-4 FORM SUB N 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
25 PRIME COMP. SUPPLIER A 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
26 COMPONENT MANUFACTURER P 4 3 5 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The inoperability of the Zone 41 early warning detectors was due to a bad wiring

11 connection on one of the detectors. The faulty wiring connection was repaired

12 and all Zone 41 detectors were returned to operable status on May 12, 1983.

13 This event is considered an isolated occurrence and no further corrective

14 action is planned.

15 FACILITY STATUS B 28 0 0 0 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
30 OTHER STATUS NA 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
31 METHOD OF DISCOVERY B 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
32 DISCOVERY DESCRIPTION Surveillance Testing 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 6016 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
33 AMOUNT OF ACTIVITY NA 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
34 LOCATION OF RELEASE NA 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 6017 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
39 0 0 0 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
40 NA 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 6018 PERSONNEL INJURIES NUMBER DESCRIPTION 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
41 0 0 0 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
42 NA 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 6019 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
43 Z 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
44 NA 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 6020 PUBLICITY ISSUED DESCRIPTION 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
45 N 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
46 NA 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

NAME OF PREPARER

H. B. RAY

PHONE

714/492-7700