

CONTROL BLOCK:

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)037CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE: 465-3550

TE22
11

USNRC REGION II
ATLANTA, GEORGIA

83 AUG 23 A9:48



August 17, 1983
PNS-LI-83-558-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 50-389-83-38

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: JULY 12, 1983

TECHNICAL SPECIFICATION 3.1.3.1

CEA POSITION

The attached Licensee Event Report has been inadvertently submitted previously on August 11, 1983 as 389-83-35.

Please find attached the Report with a corrected sequential number.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. Williams, Jr.", written in a cursive style.

J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/JEM/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 SL

OFFICIAL COPY

16-22