

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT
/0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/7/2/6/8/3/ (8) /0/8/1/7/8/3/ (9)
SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On July 26, 1983, the discharge damper for 1-HV-F-40B failed to open while run- /
/0/3/ / ning the associated safeguards area exhaust fan. This caused one Safeguards Area /
/0/4/ / Ventilation System to be inoperable which is contrary to T.S. 3.7.8.1 and report- /
/0/5/ / able pursuant to T.S. 6.9.1.9.b. The redundant SAVS was operable and the inoper- /
/0/6/ / able damper was repaired within seven days as required by the Action Statement; /
/0/7/ / therefore, the health and safety of the general public were not affected. /
/0/8/ /

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
/0/9/ /M/B/ (11)	/E/ (12)	/B/ (13)	/X/X/X/X/X/X/ (14)	/Z/ (15)	/Z/ (16)
LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.

(17) /8/3/ /-/ /0/5/3/ / / /0/3/ /L/ /-/ /0/
ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT
TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
/B/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /N/ (23) /Y/ (24) /A/ (25) /A/3/4/0/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The discharge damper, AOD-HV-1301B, had developed an air leak in the diaphragm /
/1/1/ / of the actuating mechanism. The damper was repaired, tested and returned to /
/1/2/ / service two days later. /
/1/3/ /
/1/4/ /

FACILITY STATUS	%POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
/1/5/ /E/ (28)	/1/0/0/ (29)	/ NA / (30)	/A/ (31)	/ Operator Observation /
ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)	
/1/6/ /Z/ (33)	/Z/ (34)	/ NA /	/ NA /	/
PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION (39)		
/1/7/ /0/0/0/ (37)	/Z/ (38)	/ NA /		/
PERSONNEL INJURIES NUMBER	DESCRIPTION (41)			
/1/8/ /0/0/0/ (40)	/ NA /			/
LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION (43)			
/1/9/ /Z/ (42)	/ NA /			/
PUBLICITY ISSUED	DESCRIPTION (45)			
/2/0/ /N/ (44)	/ NA /			

NRC USE ONLY

NAME OF PREPARER E. Wayne Harrell

PHONE (703) 894-5151

Vepco

USNRC REGION II
ATLANTA, GEORGIA

VIRGINIA ELECTRIC AND POWER COMPANY

03 AUG 23 09:38
NORTH ANNA POWER STATION

P. O. BOX 402

MINERAL, VIRGINIA 23117

August 17, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303

Serial No. N-83-121
NO/RST: 11
Docket No. 50-338
License No. NPF-4

Dear Mr. O'Reilly:

Pursuant to North Anna Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following License Event Report applicable to North Anna Unit No. 1.

Report No.


Applicable Technical Specifications

LER 83-053/03L-0

T.S. 6.9.1.9.b

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to Safety Evaluation and Control for their review.

Very Truly Yours



E. Wayne Harrell
Station Manager

Enclosures (3 copies)

cc: Document Control Desk (1 copy)
016 Phillips Bldg.
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY

IE 2211