

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT YEAR

17 LER/RO
REPORT
NUMBER

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							
H	18	G	19	Z	20	Z	21	0	0	0	0	N	23	N	24	Z	25	Z	9	9	9		
33		34		35		36		37		38		39		40		41		42		43		44	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause was a failure, by a contract security force member, to read and under-

1 1 stand the list of areas to be patrolled. The individual was immediately instructed

1 2 as to the location of the sign-off sheets and the coverage area. In the future,

1 3 a copy of the instructions for each new fire detail will be acknowledged by

1 4 each security member assigned to a fire detail.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 5 E 28 0 9 2 29 NA A 31 Observation

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 Z 34 NA 35

7 8 9 10 11 34

NA 36

35 36

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION
1	7	0	0	(39)
8	9	0	(37)	Z (38) NA
10	11	12	13	

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
7	8	9	11
		NA	

LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION			
1	9	Z	(42)	NA			

ISSUED DESCRIPTION (45)

2 0 N (44) NA

7 8 9 10 59

NRC USE ONLY

60 80

NAME OF PREPARER G. G. Whitney

PHONE 617-746-7900

8308310142 830809
PDR ADOCK 05000293
S PDR

TE22

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

August 9, 1983

BECO. #83-211

Regional Administrator, Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Docket No. 50-293
License DPR-35


Dear Sir:

The attached Update Licensee Event Report 83-038/03X-1, "Fire Patrol", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.c.

This Update is being issued to correct an error in the cause code (Item 12).

If there are any questions on this subject, please contact us.

Respectfully submitted,



William D. Harrington

WDH/mg

Enclosure: LER 83-038/03X-1 Update

cc: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Standard BECO. LER distribution

IE22
11