

EXPIRES 4-30-82

8309060126 830818
PDR ADCK 05000317
S PDR

LER NO. 83-39/3L
DOCKET NO. 50-317
LICENSE NO. DPR 53
EVENT DATE 07-22-83
REPORT DATE
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTION (CONT'D)

The set screws which locate and secure the condenser fan drive shaft and sheave in position had vibrated loose allowing the shaft to drop. This caused misalignment of the drive sheaves and resulted in looseness of and damage to the drive belts.

The fan drive shaft and sheave were realigned. "Loctite" was applied to the locating set screws and new belts were installed.

PM 1-30A-M-Q-1 has been revised to include visual inspection of Nos. 11 and 12 control room AC units.

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

August 18, 1983

Dr. Thomas E. Murley
Regional Administrator
U. S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA 19406

Docket No. 50-317
License No. DPR 53

Dear Dr. Murley:

Attached is LER 83-39/3L, as required by Technical Specification 6.9.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,

LBRussell
L. B. Russell
Plant Superintendent

LBR:KAR:bsb

cc: Director, Office of Management Information
and Program Control
Messrs: A. E. Lundvall, Jr.
J. A. Tiernan

IERB
11