

CP&L

Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
POST OFFICE BOX 790
HARTSVILLE, SOUTH CAROLINA 29550
AUG 24 1983

USNRC REGION II
ATLANTA, GEORGIA

Robinson File No: 13510C

Serial: RSEP/83-1112

Mr. James P. O'Reilly
Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, N. W., Suite 3100
Atlanta, Georgia 30303

B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
PROMPT NOTIFICATION - HVH COOLER LEAK

Dear Mr. O'Reilly:


In accordance with Plant Technical Specification 6.9.2.a.3, the following event is reported.

At 1215 hours on August 23, 1983, a service water leak was discovered on Containment Fan Cooler HVH-2. The service water to the cooler was isolated immediately. In accordance with Technical Specification 3.3.2.2.a, operability testing of the containment spray pumps was completed at 1402 hours. Subsequently, repairs were performed, and HVH-2 was returned to service at 2220 hours. This event is considered a degradation of a containment boundary pursuant to IE Bulletin 80-24 and is reported as such.

This event was reported on August 24, 1983, to the NRC, Region II and the office of Mr. B. J. Furr, Vice President, Nuclear Operations Department, Carolina Power and Light Company.

Very truly yours,

8309060136 830824
PDR ADOCK 05000261
S PDR


for R. B. Starkey, Jr.
General Manager
H. B. Robinson SEG Plant

HIC/bss

cc: B. J. Furr
S. P. Weise

OFFICIAL COPY

IE 22 1/0