

CONTROL BLOCK: 

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE [ 0 ] [ 9 ]		CAUSE CODE [ H ] [ H ] (11)		CAUSE SUBCODE [ E ] (12)		COMPONENT CODE [ A ] (13) [ V ] [ A ] [ L ] [ V ] [ O ] [ P ] (14)				COMP SUBCODE [ B ] (15)		VALVE SUBCODE [ Z ] (16)	
LER/O REPORT NUMBER (17) [ 8 ] [ 3 ]		EVENT YEAR [ 8 ] [ 3 ]		SEQUENTIAL REPORT NO. [ 0 ] [ 1 ] [ 0 ]		OCCURRENCE CODE [ 0 ] [ 3 ]				REPORT TYPE [ L ]		REVISION NO. [ 0 ]	
ACTION TAKEN [ B ] (18) [ G ] (19)		FUTURE ACTION		EFFECT ON PLANT [ Z ] (20)		SHUTDOWN METHOD [ Z ] (21)		HOURS [ 0 ] [ 0 ] [ 0 ] [ 0 ]		ATTACHMENT SUBMITTED [ N ] (23)		NPRO-4 FORM SUB [ N ] (24)	
PRIME COMP SUPPLIER [ L ] (25)		COMPONENT MANUFACTURER [ L ] [ 2 ] [ 0 ] [ 0 ] (25)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

8309150269 830907  
PDR ADCK 05000251  
S PDR



85 SEP 12 48:19

September 7, 1983  
PNS-LI-83-593-1

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta Street N.W., Suite 2900  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-83-10

TURKEY POINT UNIT 4

DATE OF OCCURRENCE: AUGUST 8, 1983

TECHNICAL SPECIFICATION 6.9.2.b.2

AUXILIARY FEEDWATER STEAM SUPPLY

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

J. W. Williams, Jr.  
Vice President  
Nuclear Energy

JWW/PKG/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Harold F. Reis, Esquire  
File 933.1 TP

OFFICIAL COPY

IE 22 //