


James A. FitzPatrick
Nuclear Power Plant
P.O. Box 41
Lycoming, New York 13093
315 342-3840



Harry P. Salmon, Jr.
Resident Manager

October 25, 1994
JAFF-94-0514

United States Nuclear Regulatory Commission
Document Control Desk
Mail Station P1-137
Washington, D.C. 20555

SUBJECT: DOCKET NO. 50-333
LICENSEE EVENT REPORT: 93-009-02 -

Low Reactor Water Level Scram Due to Feedwater
Transient

Dear Sir:

This report was submitted in accordance with 10 CFR 50.73
(a)(2)(iv), 10CFR50.73(a)(2)(v)(D) and 10CFR50.73(a)(2)(i)(B).

This supplement provides an updated status of the long-term
corrective actions related to this event. The replacement of the
reactor feed discharge valves with an improved design has been
scheduled so that one valve will be replaced during the 1994
Refueling Outage. The second pump discharge check valve will be
inspected during the 1994 Refueling Outage and replaced during
the 1996 Refueling Outage if supported by the inspection
findings.

Questions concerning this report may be addressed to
Mr. Donald Simpson (315) 349-6361.

Very truly yours,

HARRY P. SALMON, JR.

HPS:DFS:tlc
Enclosure

cc: USNRC, Region 1
USNRC Resident Inspector
INPO Records Center

9411030061 941025
PDR ADOCK 05000333
S PDR

IC22
11