



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401-1927  
Telephone (612) 330-5500

May 3, 1991

10 CFR Part 50  
Section 50.73

U S Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket Nos. 50-282 License Nos. DPR-42  
50-306 DPR-60

Unit 1 Reactor Trip Resulting From Loss of One  
Reactor Coolant Pump Due to Personnel Error

An updated Licensee Event Report for this occurrence is attached. The purpose of the update is to report a change to our corrective action plans.

We had stated that we would replace all aluminum bus work with copper in our 4160V buses. We planned this action in order to protect against galvanic reactions between aluminum and copper in contact with each other. During our preventive maintenance of these buses, however, we have discovered that there is aluminum bus work which is not in contact with copper. This configuration is acceptable. We, therefore, do not plan to replace aluminum bus work unless it is in contact with copper. The revised corrective action reflects this decision.

Please contact us if you require additional information related to this event.

Thomas M Parker  
Manager  
Nuclear Support Services

c: Regional Administrator - Region III, NRC  
NRR Project Manager, NRC  
Senior Resident Inspector, NRC  
MPCA

Attn: Dr J W Ferman

Attachment

9105070225 910503  
PDR ADOCK 05000282  
S PDR

TRASH AFTER FILMING

IE22

1/1