**Entergy Operations, Inc.**

River Bend Station  
5485 U.S. Highway 61  
PO Box 220  
St. Francisville, LA 70775  
(504) 336-6225  
FAX (504) 635-5068

**JAMES J. FISICARO**

Director  
Nuclear Safety

November 2, 1994

U.S. Nuclear Regulatory Commission  
Document Control Desk  
M/S P1-37  
Washington, D.C. 20555

Subject: River Bend Station - Unit 1  
Docket No. 50-458  
License No. NPF-47  
Inservice Inspection Summary Report  
File Nos.: G9.5, 224.600

RBG-41036  
RBF1-94-0059

Gentlemen:

In accordance with 10CFR50.55a, Entergy Operations, Inc., (EOI) hereby submits the Inservice Inspection Summary Report for the River Bend Station (RBS) inservice inspection performed during the fifth refueling outage (RF-5). This report is submitted for your information pursuant to ASME Boiler and Pressure Vessel Code, Section XI-Division I, Subarticle IWA-6230, 1980 Edition with Addenda through Winter 1981.

ASME Section XI, IWA-6230, "Summary Report Submittal," states that an inservice inspection summary report shall be filed with the enforcement and regulatory authorities having jurisdiction at the plant site within 90 days of the completion of the inservice inspection conducted during a refueling outage. RF-5 was completed on July 6, 1994. Therefore, the RBS filing date for this summary report would have been October 4, 1994. However, the submittal was delayed due to an extended forced outage from September 8, 1994, through October 24, 1994. As described in Licensee Event Report 94-023, the scram investigation was very extensive.

Per conversation between Mr. R. Schaaf of your staff and Mr. G. Davant of my staff on September 29, 1994, the submittal date for the Inservice Inspection Summary Report was extended 30 days. Your cooperation regarding EOI's request is greatly appreciated. This provided the time necessary for Inservice Inspection personnel to address the outage-related

9411100269 941102  
PDR ADOCK 05000458  
Q PDR

A041  
1/1

Inservice Inspection Summary Report

November 2, 1994

RBG- 41036


RBFI-94-0059

Page 2 of 2

inspections. Once the outage was completed on October 24, 1994, attention was again focused on completion of the Inservice Inspection Summary Report.

If you have further questions regarding this request, or require additional information, please contact me or my staff.

Very truly yours,



JJF\jcm  
enclosure

cc: U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

NRC Sr. Resident Inspector  
P.O. Box 1051  
St. Francisville, LA 70775

Mr. David Wigginton  
U.S. Nuclear Regulatory Commission  
M/S O 13-H-3  
Washington, D.C. 20555