

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)01 M A P P S I 2000-000000-000341111145  
7 8 9 14 15 25 26 30 57 58CONT  
01 REPORT SOURCE L 6050-0293706178380714839  
7 8 60 61 68 69 74 75 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On 6/17/83, fire door #64 between the emergency diesel generator air compressor  
03 rooms was found to be not capable of being latched properly, as required by  
04 T.S. 3.12.F. A fire patrol was initiated and a maintenance request submitted.  
05 This event caused no threat to the public health and safety. LER 81-035 re-  
06 ported a similar event. The subject door of the 1981 LER has since been re-  
07 placed with a new design supplied by Construction Specialties Co., Inc.

08  
09 SYSTEM CODE A B 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 18 19 20  
17 LER/RO REPORT NUMBER 83 21 EVENT YEAR 83 22 SEQUENTIAL REPORT NO. 037 23 OCCURRENCE CODE 03 24 REPORT TYPE L 25 REVISION NO. 0  
21 22 23 24 26 27 28 29 30 31 32  
18 ACTION TAKEN E 19 FUTURE ACTION Z 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 22 HOURS 0000 23 ATTACHMENT SUBMITTED N 24 NPRO-4 FORM SUB. N 25 PRIME COMP. SUPPLIER Z 26 COMPONENT MANUFACTURER X999  
33 34 35 36 37 40 41 42 43 44 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The door latch was found to require an adjustment to allow proper closure and  
11 latching. To maintain the 3 hour rating of this door, the adjustment presently  
12 must be made by the vendor. The fire patrol will be maintained until adjustment  
13 is made.

14  
15 FACILITY STATUS E 28 % POWER 095 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Observation 32  
7 8 9 10 11 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36  
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION N/A 39  
7 8 9 10 11 12 13 80

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION N/A 41  
7 8 9 10 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43  
7 8 9 10 80

20 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45  
7 8 9 10 80

NAME OF PREPARER G. G. Whitney

PHONE (617)746-7900

8307220331 830714  
PDR ADOCK 05000293  
S PDRIE22  
1/1

BOSTON EDISON COMPANY  
800 BOYLSTON STREET  
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON  
SENIOR VICE PRESIDENT  
NUCLEAR

July 14, 1983

BECO. Ltr. #83-185

Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Docket No. 50-293  
License DPR-35

Dear Sir:

The attached Licensee Event Report 83-037/03L-0, "Fire Door #64 Latch", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.b.

If there are any questions on this subject, please contact us.

Respectfully submitted,

*W D Harrington*

William D. Harrington

WDH/mg

Enclosure: LER 83-037/03L-0

cc: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Standard BECo. LER Distribution

*Ter*  
*1/1*