

July 11, 1983

Richard W. Starostecki, Director
Division of Project and Resident Programs
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

RE: Docket No. 50-220
Inspection Report 83-08

Dear Mr. Starostecki,

This refers to the routine, safety inspection conducted by Mr. S. Hudson of your staff on April 1-30, 1983 at Nine Mile Point Unit #1, Scriba, New York of activities authorized by NRC License No. DPR-63, and to the discussions of your findings held by Mr. S. Hudson with Mr. T. Roman of our staff at the conclusion of the inspection.


Item A

Technical Specification 6.8.1 states in part: "Written procedures and administrative policies shall be established, implemented and maintained..." Administrative procedure APN-7A, "Placement of Jumpers and Blocks or Lifting of Leads", Revision 8 dated September 7, 1982, Section 4.1, requires that jumpers be identified with a serial number. Section 4.3.3 states in part: "After restoration, the person performing and the person verifying shall sign the jumper/block log..."

Contrary to the above, on April 27, 1983, two jumpers - one of which was not numbered - were found to be installed although jumper log #1392 indicated that they were removed on April 13, 1983.

RESPONSE

This incident was discussed with the individuals involved and the importance of strict adherence to the jumper/block log procedures APN-7A was stressed. The procedure was also reviewed with them. Subsequent to this event a review of all safety related systems was performed prior to start up which assured that no other unauthorized jumpers or lifted leads existed.

Very truly yours,

Thomas E. Lempges
Vice President
Nuclear Generation

TEL/DK/bg