


**LOUISIANA
POWER & LIGHT**

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345



July 15, 1983

W3I83-0236
Q-3-A35.07.60

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 60
"Turnover Documentation and Inadequate
Hanger Weld Problems T-B"
Fourth Interim Report

REFERENCE: LP&L letter W3I83-0158 dated May 11, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than July 15, 1983.

At the present time, corrective action is ongoing and the supporting documentation review is in progress. Completion of the corrective action and documentation review is scheduled for August 17, 1983.

A Final Report will therefore be submitted to the USNRC by September 16, 1983.

Very truly yours,

Thomas F. Drummond for

F. J. Drummond
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

3) Mr. E. L. Blake

4) Mr. W. M. Stevenson

8307260392 830715
PDR ADOCK 05000382
S PDR

IE-27

1/0