

Updated Report

Previous Report Date 6/14/83

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

CONT

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	3	7	7	0	4	2	6	8	3	3	0	7	1	9	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 | During normal operation, operator observed narrow range Gemac (2-640-29A) and

0 3 | wide range Yarway (2-263-106A) reactor water level indicators pegged high. (Tech

0 4 | Spec Table 3.2.2). Safety significance was minimal since redundant level

0 5 | indicators were functioning properly. No effect on public health or safety. First

0 6 | occurrence of this type.

0 7 |

0 8 |

80

09		SYSTEM CODE IA		11	CAUSE CODE E		12	CAUSE SUBCODE B		13	COMPONENT CODE INSTRU						14	SUBCODE S		15	SUBCODE Z		16
7		8		9		10		11		12		13		14		15		16		17		18	
17		LER/RO REPORT NUMBER		EVENT YEAR 83		21		22		23		24		25		26		27		28		29	
30		ACTION TAKEN		FUTURE ACTION		33		34		35		36		37		38		39		40		41	
42		EFFECT ON PLANT Z		20		43		44		45		46		47		48		49		50		51	
52		SHUTDOWN METHOD Z		21		53		54		55		56		57		58		59		60		61	
62		HOURS 0000		22		63		64		65		66		67		68		69		70		71	
72		ATTACHMENT SUBMITTED N		23		73		74		75		76		77		78		79		80		81	
82		NPRD-4 FORM SUB. N		24		83		84		85		86		87		88		89		90		91	
92		PRIME COMP. SUPPLIER N		25		93		94		95		96		97		98		99		100		101	
102		REVISION NO. 2		32		103		104		105		106		107		108		109		110		111	
112		COMPONENT MANUFACTURER B069		26		113		114		115		116		117		118		119		120		121	
122		CAUSE DESCRIPTION AND CORRECTIVE ACTIONS		27		123		124		125		126		127		128		129		130		131	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Cause of the event was due to a loose packing nut on pressure switch 2-263-111A
1	1	(Model 82T-M12SS-GE), which allowed water to drain from the reference legs of
1	2	both level instruments. The packing nut was tightened and both level indicators
1	3	functioned properly. No further action deemed necessary.
1	4	

7 8 9
FACILITY STATUS (28) 1 5 F
% POWER 10 12 13 29 N/A
OTHER STATUS (30)
METHOD OF DISCOVERY (31) A
DISCOVERY DESCRIPTION (32) Operator Observation
ACTIVITY CONTENT
RELEASED OF RELEASE (33) 1 5 Z
AMOUNT OF ACTIVITY (35) 10 11 34 N/A
LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES

MBER			TYPE	DESCRIPTION
1	7	0 0 0	(37) Z	(38) N/A (39)

7		8		9		11		12		13	
PERSONNEL INJURIES											
NUMBER						DESCRIPTION (41)					
1	3	0	0	0	(40)	N/A					

7		8	9	11		12
LOSS OF OR DAMAGE TO FACILITY (43)						
TYPE		DESCRIPTION				
1	9	Z	(42)	N/A		

7 8 9 10
PUBLICITY
ISSUED DESCRIPTION (45)
2 0 N (44) N/A
8308040232 830719
PDR ADOCK 05000237
S PDR
NRC USE ONLY
68 69
(215) 042-2020-526

NAME OF PREPARER Lawrence M. Coyle

PHONE: (815) 942-2920 x526

SUPPLEMENT TO DVR

DVR NO.	STA	UNIT.	YEAR	NO.
D -	12	-	2	- 83 - 71

PART 1	TITLE OF EVENT	OCCURRED	
	Wide Range Yarway and Narrow Range Gemac Pegged High	4-26-83 DATE	2100 TIME
REASON FOR SUPPLEMENTAL REPORT			
Supplemental issued to correct the LER number on the Licensee Event			
Report sheet.			
PART 2			
ACCEPTANCE BY STATION REVIEW	<i>J. Bruner</i>	<i>John A. Almer</i>	
DATE	7/19/83	7/20/83	
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<i>R.M. Pappas Jr</i>	7/20/83	
	STATION SUPERINTENDENT	DATE	



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

July 19, 1983

DJS Ltr #83-710

James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #83-43/03X-2, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation. This supplement is being issued to correct the LER/RO report number - Item 17 on Licensee Event Report sheet.

D.J. Scott

D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

JUL 25 1983

11 FE22