

**LICENSEE EVENT REPORT**

UPDATE REPORT: Previous Report  
Date 8/13/82

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 IAOAC1 200-000000-000 3411111111 4111111111

LICENSE CODE 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CON'T

01 L605000331707198280715839

REPORT SOURCE 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90

DOCKET NUMBER 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90

EVENT DATE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90

REPORT DATE 80 81 82 83 84 85 86 87 88 89 90

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During unit startup, IRM E & F were inop. at 1920 hrs, IRM D failed STP-  
03 42A001 and was bypassed. Contrary to T.S.3.1.A, two IRMs were not operab  
04 le in RPS B. IRM F was returned to service at 2010 hrs. IRM F inop again  
05 on 7/20/82 at 2100 hrs. An RPS B half scram was initiated. At 2220 hrs t  
06 he mode SW was placed in shutdown. IRM B & D functioned properly during  
07 subsequent startup. These actions per T.S., therefore the health & safet  
08 y of the plant personnel & public were not jeopardized. (Ref AO 74-43)

09 IB11 D12 Z13 INSTRU14 E15 Z16

SYSTEM CODE 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE CODE 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE SUBCODE 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

COMPONENT CODE 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

VALVE SUBCODE 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 E18G19 Z20 Z21 0000 N22 N23 N24

DmB

Iowa Electric Light and Power Company

July 15, 1983  
DAEC-83-552

Mr. James G. Keppler  
Regional Administrator  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137


Subject: Licensee Event Report No. 82-048 UPDATE REPORT:  
(30 day) Previous Report  
Date 8/13/82

File: A-118a, TE-2

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications, Section 6.11.2.b(3), and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report.

Very truly yours,



Daniel L. Mineck  
Plant Superintendent - Nuclear  
Duane Arnold Energy Center

DLM/GAR/pf\*

Docket 50-331

attachment

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector - DAEC

JUL 20 1983

11 IE22