

**Detroit
Edison**

Donald A. Wells
Manager Quality Assurance
(313) 237-9657

2000 Second Avenue
Detroit, Michigan 48226
(313) 237-8090

July 11, 1983
EF2-64306

Mr. James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Final Report of Potential 10CFR50.55(e) Item on Apparent Acts of
Vandalism to Relay Room Cabinet (#96)

Dear Mr. Keppler:


This is Detroit Edison's final report involving apparent acts of vandalism to a relay room cabinet. This item was originally reported to Mr. H.M. Wescott of NRC Region III by Detroit Edison's Mr. W.E. Miller, Jr., Supervisor - Construction Quality Assurance on June 10, 1983.

It was discovered that four (4) coaxial cables (231257-1K, 231-258-1K, 231267-1K and 231268-1K) in relay room cabinet H11-P914 were cut or pulled out of their terminated location. This had resulted in damaged cables. In addition, it appeared that some of the pin assemblies on the ends of the cables were still in the receptacles, which may have caused damage to the receptacles.

Detroit Edison's evaluation of the damage to the cables and receptacles determines this item non-reportable per 10CFR50.55(e) requirements.

If you have questions concerning this matter, please contact Mr. G.M. Trahey, Assistant Director - Project Quality Assurance.

Very truly yours,



DAW/WEM/pn

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Bruce Little, Senior Resident Inspector
U.S. Nuclear Regulatory Commission
6450 North Dixie Highway
Newport, Michigan 48166

8308040329 830711
PDR ADDOCK 05000341
S PDR

1/0 IE27 JUL 20 1983