



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 713-838-6631

August 2, 1983

RBG- 15,572

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-119

On May 17, 1983, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning the failure of threaded weld studs during the construction of cable tray supports (DR-119). GSU is awaiting the results of additional Quality Assurance evaluation by our architect-engineer. An interim or final status report will be provided by September 7, 1983.

Sincerely,

William J. Leedy
for J. E. Booker

Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

ATD
JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)