

CONTROL BLOCK: 

--	--	--	--	--	--	--

 (1)

0 1 T N S N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
2 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 56

0 1  
2 8

REPORT SOURCE L 6 0 5 0 0 0 3 2 7 7 0 7 0 6 8 3 8 0 8 0 3 8 3 9  
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES	
02	Unit 1 in mode 1 at 98% RTP. Containment vacuum relief valve 1-30-571 was declared

inoperable at 1605 CDST on 07/06/83 due to containment vacuum relief isolation

valve, 1-FCV-30-46, being discovered failed closed. This event required entry

into LCO 3.6.6.1. There was no effect upon public health and safety. Previous

occurrences - none.

63

\_\_\_\_\_

7	8	9	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
---	---	---	----------------	---------------	------------------	----------------	------------------	------------------

0 9 10 11 12 13 14 15 16 17 18 19 20

(17) LER/RO REPORT NUMBER

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER		
X	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	N	24	L	25	P	3	4
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Plant maintenance personnel checked the isolation valve, 1-FCV-30-46; and no
---	---	--

malfunctions or failures were found. The valve was stroked six times and returned

to service on 07/06/83 at 1855 CDST. This event is considered an isolated incident

1 3 and no additional corrective actions will be taken unless the problem recurs.

1.4

FACILITY STATUS	POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION

1 5 E 28 0 9 8 29 NA A 31 Operator observation

ACTIVITY	CONTENT	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
RELEASED	OF RELEASE	(35)	(36)

1	6	Z	33	Z	34	NA	NA
---	---	---	----	---	----	----	----

PERSONNEL EXPOSURES	NUMBER	TYPE	DESCRIPTION
			(39)

1 7 0 0 0 7 2 38 NA

PERSONNEL INJURIES	
NUMBER	DESCRIPTION (41)

1 8 0 0 0 40 NA 830803

LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION

1 9 2 42 NA S

TO PUBLICITY  
ISSUED DESCRIPTION (45) NRC USE ONLY

2 0 N 44 NA

Phone: (615) 870-6422

TENNESSEE VALLEY AUTHORITY

AT CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

83 AUG 4 A10:18

August 3, 1983

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE  
REPORT SQRO-50-327/83091

The enclosed report provides details concerning the inoperability of  
containment vacuum relief valve 1-30-571. This report is submitted in  
accordance with Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
H. J. Green  
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

NRC Inspector, Sequoyah

OFFICIAL COPY

IE22