

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

NARRATIVE REPORT
FOR LER 50-366/1983-078

LICENSEE : GEORGIA POWER COMPANY
FACILITY NAME : EDWIN I. HATCH
DOCKET NUMBER : 50-366

Tech. Specs. section(s) which requires report:

This 30-day LER is required by Tech. Specs. section 6.9.1.9.c because it showed that administrative controls were not being complied with.

Plant conditions at the time of the event(s):

The plant was in the shutdown mode when these events occurred.

Detailed description of the event(s):

On 08/04/83, during compliance with standing order number 83-33 (VALVE POSITION SEALING), it was discovered that five drywell pneumatic system drain valves were closed, but not locked and sealed as required by the "DRYWELL PNEUMATIC SYSTEM" procedure (HNP-2-1473). This event is contrary to Tech. Specs. section 6.9.1.9.c. These five valves were: 2P70-F076B, 2P70-F076D, 2P70-F076F, 2P70-F076G, and 2P70-F079C.

Consequences of the event(s):

This event did not affect plant operations, because the unit was in the shutdown mode when the event occurred. The health and safety of the public were not affected by this event.

Status of redundant or backup subsystems and/or systems:

There is no backup system for these valves.

Justification for continued operation:

No justification was necessary because the unit was in the shutdown mode.

If repetitive, number of previous LER:

This event is non-repetitive, but a similar event occurred on Unit 1 as last reported on LER 50-321/1983-049.

Impact to other systems and/or Unit:

This event had no impact upon other systems in Unit 2, or Unit 1.

Cause(s) of the event(s):

An investigation revealed that this event was caused by a personnel error of persons unknown.

Immediate Corrective Action:

The valves were immediately locked and sealed as required by HNP-2-1473, on 08/04/83.

Supplemental Corrective Action:

No supplemental corrective action is necessary.

Scheduled (future) corrective action:

No future corrective action is scheduled.

Action to prevent recurrence (if different from corrective actions):

N/A

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444

Edwin I. Hatch Nuclear Plant

September 1, 1983
GM-83-856




PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-366

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Attached is Licensee Event Report No. 50-366/1983-078. This report is required by Hatch Unit 2 Technical Specifications Section 6.9.1.9.c.


H. C. Nix
General Manager

^{JE}
HCN/SBT/djs

xc: R. J. Kelly
G. F. Head
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
S. B. Tipps
R. D. Baker
Control Room
Document Control

OFFICIAL COPY

JE 22
|||