



# MISSISSIPPI POWER & LIGHT COMPANY

*Helping Build Mississippi*

P. O. BOX 1640 JACKSON, MISSISSIPPI 39205

83 SEP 20 11:24  
September 14, 1983

NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 2900  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-13  
File 0260/L-835.0  
Special Report 83-081/0 - Fire  
Damper Discovered Damaged,  
Fire Damper Flashing  
Discovered Unbolted  
AECM-83/0576

On August 16, 1983, during a scheduled eighteen month surveillance, the flashing around fire damper 1Z77F009 was discovered not bolted to the wall and fire damper 1Z77F014 would not close due to a bent guide track. The requirements of Technical Specification 3.7.7, Action (a), were met and the required hourly fire watches were conducted until the subject fire rated assemblies were restored to operability.

The flashing around 1Z77F009 was bolted back to the wall on August 17, 1983. The cause was attributed to construction error.

Fire damper 1Z77F014 was repaired on August 27, 1983. The guide was apparently bent during construction activities in the immediate area.

This is reported pursuant to Technical Specification 6.9.2. This had no effect on the health or safety of the public nor did it threaten plant safety. This is a final report.

Yours truly,

for L. F. Dale  
Manager of Nuclear Services

EBS/SHH:sap

cc: (See Next Page)

8309230308 830914  
PDR ADOCK 05000416  
S PDR

member Middle South Utilities System

OFFICIAL COPY  
IC 22

MISSISSIPPI POWER & LIGHT COMPANY

AECM-83/0576

Page 2

cc: Mr. J. B. Richard  
Mr. R. B. McGehee  
Mr. T. B. Conner  
Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555