

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35											
LICENSEE CODE															LICENSE NUMBER										LICENSE TYPE										CAT 58				

CONT

0	1	L	6	0	5	0	0	0	3	1	6	7	0	9	1	2	8	3	8	1	0	0	5	8	3	9																		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35																
REPORT SOURCE															DOCKET NUMBER										EVENT DATE										REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING A Q.A. TOUR OF CONTROL ROOM, A NON-FUNCTIONAL FIRE SEAL WAS DISCOVERED.

0 3 DAMAGE TO THE FIRE SEAL WAS LIMITED TO A VERY SMALL AREA AROUND THE CABLE.

0 4 THE CONDITION WAS NONCONSERVATIVE WITH RESPECT TO T.S. 3.7.10. THE ACTION

0 5 REQUIREMENTS WERE MET. PREVIOUS SIMILAR EVENTS INCLUDE 315/79-044,055; 315/81-

0 6 051,055 316/81-051; 315/82-055,069,070 316/82-103; 315/83-026 316/83-008,030.

0 7

0 8

0	9	A	B	11	A	12	E	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16	17	8	3	18	0	8	8	19	0	3	20	L	21	0	22	0	23	N	24	N	25	Z	26	9	9	9	27
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50			
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE										COMP. SUBCODE		VALVE SUBCODE		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.																		
LER/RO REPORT NUMBER		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																												

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 INVESTIGATION FOUND THAT A FIRE SEAL REPAIR HAD BEEN PULLED FROM FIRE SEAL WHILE

1 1 INSTALLING ANOTHER CABLE. A FIREWATCH WAS IMMEDIATELY POSTED UNTIL THE FIRE SEAL

1 2 WAS REPAIRED. TRAINING HAS BEEN CONDUCTED WITH CONTRACTOR PERSONNEL REGARDING

1 3 CARE IN HANDLING EXISTING CABLE DURING NEW CABLE INSTALLATION.

1 4

1	5	E	28	1	0	0	29	NA	30	B	31	Q.A. AUDIT	32	NA	33	NA	34	NA	35	NA	36	NA	37	0	38	NA	39	0	40	NA	41	0	42	NA	43	0	44	NA	45	NA	46	NA	47	NA	48	NA	49	NA	50
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50						
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		ACTIVITY		CONTENT		RELEASED		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		PERSONNEL EXPOSURES		TYPE		DESCRIPTION		PERSONNEL INJURIES		TYPE		DESCRIPTION		LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION		PUBLICATION		ISSUED		DESCRIPTION							

NAME OF PREPARER H.L. SMITHPHONE 616-465-5901

NRC USE ONLY