

THE TOLEDO EDISON COMPANY  
DAVIS-BESSE NUCLEAR POWER STATION  
EMERGENCY PLAN SUPPORTING PROCEDURES  
REVISION INDEX

| <u>Page</u> | <u>Revision</u> | <u>Procedures</u> | <u>Revision</u> | <u>Temporary Modification</u> |
|-------------|-----------------|-------------------|-----------------|-------------------------------|
| 1           | 7               | HP 1602.01        | 14              |                               |
|             |                 | HP 1604.01        | 5               |                               |
|             |                 | HP 1604.02        | 0               |                               |
|             |                 | AD 1827.01        | 4               |                               |
|             |                 | AD 1827.02        | 10              |                               |
|             |                 | AD 1827.03        | 3               |                               |
|             |                 | AD 1827.04        | 2               |                               |
|             |                 | AD 1827.05        | 2               |                               |
|             |                 | AD 1827.06        | 2               | T-7248                        |
|             |                 | AD 1827.07        | 3               | T-7480                        |
|             |                 | AD 1827.08        | 2               |                               |
|             |                 | AD 1827.09        | 2               |                               |
|             |                 | AD 1827.10        | 13              |                               |
|             |                 | AD 1827.11        | 5               |                               |
|             |                 | AD 1827.12        | 10              |                               |
|             |                 | AD 1827.13        | 6               |                               |
|             |                 | AD 1827.15        | 5               |                               |
|             |                 | AD 1827.16        | 2               |                               |
|             |                 | AD 1827.17        | 5               |                               |
|             |                 | AD 1850.04        | 7               |                               |
|             |                 | AD 1850.05        | 7               |                               |
|             |                 | AD 1850.06        | 2               | T-7399                        |

Administrative Memorandums

|        |                                  | <u>Revision</u> |
|--------|----------------------------------|-----------------|
| No. 37 | ECS Pager and Telephone Numbers  | 30              |
| No. 38 | First Aid Team                   | 12              |
| No. 39 | Fire Brigade                     | 16              |
| No. 41 | Emergency Duty Officer (EDO)     | 28              |
| No. 42 | Radiation Monitoring Teams (RMT) | 19              |

Revision 191  
September, 1983

8310210363 831018  
PDR ADOCK 05000346  
F PDR

X005

## DISTRIBUTION



Original, Responsible Section Head Action



File Copy, Master File

DAVIS-BESSE NUCLEAR POWER STATION - UNIT 1  
TEMPORARY MODIFICATION REQUEST

ED 6926

T-7480

COPIES TO BE MODIFIED FOR IMMEDIATE IMPLEMENTATION

Control Room Shift Supervisor  
Control Room Files (as required)

## SECTION 1

## PROCEDURE TITLE AND NUMBER

Earthquake, AD 1827.07

## REASON FOR CHANGE

The seismic qualification of the temperature switches for the service water ventilation fans has not yet been received. Therefore, if an earthquake occurs, the ventilation fans must be locally verified to be operating properly. CORRECTIVE ACTION PER SAFETY EVALUATION ATTACHED TO NCR 83-20.

## CHANGE

Add to Step 5.2.2 - 1

Periodically verify the service water ventilation is maintaining proper room temperature or place the units in manual and verify the ventilation fans are operating.

IS PROCEDURE REVISION REQUIRED

Yes ☐No ☒

If no, this modification is valid until

Seismic qualification  
received per SDR 2118

|   |                      |      |         |
|---|----------------------|------|---------|
| PREPARED BY                                   | <i>Star Batch</i>    | DATE | 9/22/83 |
| APPROVED BY                                   | <i>John L. Fitt</i>  | DATE | 9/22/83 |
| APPROVED BY                                   | <i>M. Deism</i>      | DATE | 9-22-83 |
| SUBMITTED BY (Section Head)                   | <i>BT Bey</i>        | DATE | 9/22/83 |
| RECOMMENDED BY (SRB Chairman)                 | <i>Sam Deism</i>     | DATE | 9/27/83 |
| QA APPROVED BY (Manager of Quality Assurance) | <i>22 Dept / C/H</i> | DATE | 9/27/83 |
| APPROVED BY (Station Superintendent)          | <i>Tom Murray</i>    | DATE | 9/27/83 |

DAVIS-BESSE REVISION COVER SHEET

September 30, 1983

DATE

TO: Dir of RRC

FROM: EMERGENCY PLANNING & PREPAREDNESS SUPV.

SUBJECT: Davis-Besse EMERGENCY PLAN SUPPORTING PROCEDURES Manual Changes

This letter transmits additions and revisions to the Davis-Besse

EMERGENCY PLAN SUPPORTING PROCEDURES Manual. Control Copy 50A.

Instructions for the material are as follows:

REMOVE AND RETURN

INSERT

Revision Index, Revision 190

Revision Index, Revision 191

T-7480 in front of AD 1827.07

Date Revision Entered \_\_\_\_\_

Addressee Signature \_\_\_\_\_

RETURN TO THE OFFICE MANAGER - STOP #3050

X005  
1/2