

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | MIDICIC1 | 200-000000-000 | 34111114 | 115

CON'T

01 | L60500003115 | 71216813 | 5011084 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

012 | DURING REPLACEMENT OF MIRROR INSULATION OF THE PORV'S, THE CABLE FOR ACOUSTIC VALVE  
013 | MONITOR ACCELEROMETER (SV-45b) WAS CUT. THIS EVENT WAS NON-CONSERVATIVE WITH RESPECT  
014 | TO TECHNICAL SPECIFICATION 3.3.3.8. THE ACTION REQUIREMENT WAS MET. PUBLIC HEALTH  
015 | AND SAFETY WERE NOT AFFECTED.

016 |

017 |

018 |

019 |

012 | IE11 | A12 | F13 | INISITIRU14 | E15 | Z16

17 | 83 | 123 | 013 | L | 0  
B13 | F19 | Z20 | Z21 | 000000 | N23 | N24 | A25 | X9999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

110 | NEW CABLE WAS INSTALLED, MONITOR WAS VERIFIED TO OPERATE CORRECTLY AND RETURNED TO  
111 | SERVICE. TO PREVENT RECURRENCE, INSULATING PERSONNEL HAVE BEEN CAUTIONED TO EXERCISE  
112 | EXTREME CARE WHEN WORKING IN THE AREA OF THE MONITORING EQUIPMENT. IN ADDITION, A  
113 | DESIGN CHANGE HAS BEEN REQUESTED TO ADD PROTECTION TO THE MONITORING EQUIPMENT.

114 |

115 | G23 | 000029 | NA30 | B31 | OPERATOR OBSERVATION32

116 | Z33 | Z34 | NA35 | NA36

117 | 000037 | Z38 | NA39

118 | 000040 | NA41

119 | Z42 | NA43

120 | N44 | NA45

121 | N44 | NA45

122 | N44 | NA45

123 | N44 | NA45

124 | N44 | NA45

8401190374 840110  
 PDR ADOCK 05000215  
 S PDR

NRC USE ONLY

NAME OF PREPARED R. A. PALMER

(616)465-5901