



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

February 14, 1983

L. V. MAURIN
Vice President Nuclear Operations

W3I83-0050
Q-3-A35.07.48

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 48
"Design Application of Break Flanges at Elevated Temperatures"

REFERENCE: LP&L letter W3I83-0017 dated January 24, 1983

Dear Mr. Collins:

The above referenced letter reopened SCD 48 because the scope of the corrective action was not adequately reflected in the final report. At the present time, review of the documentation is still ongoing. It is anticipated that this review will be completed and a final report submitted by February 28, 1983.

Very truly yours,

L. V. Maurin

IF-27

LVM/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) E. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) W. Stevenson