

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

February 1, 1984

BLRD-50-438/82-04

BLRD-50-439/82-04

U.S. Nuclear Regulatory Commission
Region II

Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - BONNET STUDS IMPROPERLY TORQUED ON
DECAY HEAT REMOVAL VALVES - BLRD-50-438/82-04, BLRD-50-439/82-04 -
SECOND SUPPLEMENTAL REPORT


The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on December 22, 1981 in accordance with 10 CFR 50.55(e) as NCR 1686. This was followed by our interim reports dated January 20, April 15, June 28, August 24, and November 1, 1982 and January 10, 1983, our final report dated April 13, 1983 and our first supplemental report dated December 22, 1983. Below is our second supplemental report. We consider 10 CFR Part 21 applicable to this deficiency.

As discussed with NRC-OIE Inspector D. M. Verrelli on January 16, 1984, the date of January 16, 1984 for completion of corrective actions indicated in our final report on this matter was not met. Several bonnet studs were missing when the craftsmen went to retorque the nuts necessitating procurement of replacement studs. The corrective action on this matter will be completed by September 15, 1984.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8402140432 840201
PDR ADOCK 05000438
S PDR

110
OFFICIAL COPY

JE27