

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 372-3531

84 FEB 13 10:32 1984


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30303

Re: Catawba Nuclear Station  
Unit 2  
Docket No. 50-414

Dear Mr. O'Reilly:

In the Corrective Action section of Significant Deficiency Report No. SD 414/83-17, it was stated that the three welding boss restrictors have been installed as required by design drawing, but that one additional discrepancy was found which was documented on NCIR 17679. The pipe work required for this remaining item will be completed by March 30, 1984. Training of all appropriate personnel was completed by January 16, 1984 as committed.

Very truly yours,



Hal B. Tucker

LTP/php

cc: Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector  
Catawba Nuclear Station

Palmetto Alliance  
2135 1/2 Devine Street  
Columbia, South Carolina 29205

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

Mr. Robert Guild, Esq.  
Attorney-at-Law  
P. O. Box 12097  
Charleston, South Carolina 29412

8402150357 840203  
PDR ADDCK 05000414  
S PDR

OFFICIAL COPY

1627

1/0