

DmB

SNUPPS

Standardized Nuclear Unit
Power Plant System

5 Choke Cherry Road
Rockville, Maryland 20850
(301) 869-8010

February 13, 1984

SLNRC 84-0031 FILE: 0491.10.2
SUBJ: Significant Deficiency Report (SDR)
83-13: Limitorque Valve Operator
Limit Switch Rotor Material

Mr. James G. Keppler
Administrator, Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Mr. John T. Collins
Administrator, Region IV
U.S. Nuclear Regulatory Commission
Suite 1000, Parkway Central Plaza
Arlington, Texas 76012

Docket Nos. STN 50-482 and STN 50-483


Reference: SLNRC 83-0064, 12/22/83: Subject as Above

Gentlemen:

The reference letter provided an interim report of a generic significant deficiency at Callaway and Wolf Creek plants involving cracks in certain limit switch rotors used in Limitorque valve actuators. The reference further indicated that a final report would be available within 60 days. Please be advised that because of complications in fully resolving the described deficiency, a final report will not be available until March 31, 1984.

We regret any inconvenience which may result from this delay.

Very truly yours,


S. J. Seiken
Manager, Quality Assurance

SJS/dck24b13

cc: D. T. McPhee, KCPL
G. L. Koester, KGE
D. F. Schnell, UE
H. W. Roberds, USNRC/WC
J. H. Neisler, USNRC/Cal
B. H. Little, USNRC/Cal
J. E. Konklin, USNRC Region III
Richard DeYoung, Director I&E
Record

8402220062 840213
PDR ADDCK 05000482
S PDR

FEB 16 1984

IE19/10