

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)

Joseph M. Farley - Unit 2

DOCKET NUMBER (2)

0 5 0 0 0 3 6 4

PAGE (3)

1 OF 02

TITLE (4)

Missed Firewatch Patrol

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)	
01	24	84	84	002	00	02	23	84			050000	
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)									
POWER LEVEL (10)			20.402(b)			20.405(c)			50.73(a)(2)(iv)			73.71(b)
100			20.405(a)(1)(i)			50.38(c)(1)			50.73(a)(2)(v)			73.71(c)
			20.405(a)(1)(ii)			50.38(c)(2)			50.73(a)(2)(vii)			OTHER (Specify in Abstract below and in Text, NRC Form 366A)
			20.405(a)(1)(iii)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(A)			
			20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)			
			20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(ix)			

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
W. G. Hairston, III	AREA CODE 205 899-5156

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 1500 on 1/23/84, it was determined that an hourly firewatch patrol in the B train auxiliary building battery charger room, as required by Technical Specification 3.3.3.9, had not been performed during the 1300-1400 and 1400-1500 hours. The firewatch patrol was immediately performed for the 1500-1600 hour and all subsequent hours as required. Health/safety of the public was not affected.

8402270262 840223  
PDR ADOCK 05000364  
S PDR

IE22

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

Joseph M. Farley - Unit 2

0 5 0 0 0 3 6 4 8 4 — 0 0 2 — 0 0 0 2 OF 0 2

TEXT (If more space is required, use additions NRC Form 365A's) (17)

At 1500 on 1-23-84, an offgoing system operator notified the control room that he had failed to perform an hourly firewatch patrol in the B train auxiliary building battery charger room for the 1300-1400 and 1400-1500 hours. An oncoming system operator was immediately sent to the area to perform the firewatch patrol for the 1500-1600 hour. The firewatch patrol was performed correctly until no longer required.

This event was caused by personnel error. The individual assigned to the firewatch patrol became involved in other work and failed to perform the firewatch patrol. The individual involved has been counseled concerning the necessity of performing required firewatch patrol or of notifying the control room so that other personnel may perform them.

Mailing Address  
Alabama Power Company  
600 North 18th Street  
Post Office Box 2641  
Birmingham, Alabama 35291  
Telephone 205 783-6081

F. L. Clayton, Jr.  
Senior Vice President  
Flintridge Building



February 23, 1984

Docket No. 364


Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 2, Licensee Event Report No. LER 84-002-00 is forwarded in accordance with 10CFR50.73 to provide 30 day written notification of this occurrence. This report was prepared using a draft version of IEEE Std. 805-1984 since a final version has not been published.

If you have any questions, please advise.

Yours very truly,

*for*   
F. L. Clayton, Jr.

FLCJr/KWM:sam

Enclosures

xc: IE, Region II

IE22  
11