

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

22 NRC USE ONLY
68 50
(416 888-2560)
PHONE

November 18, 1983

Docket No. 50-305

LER 83-024/03L-0

Kewaunee Nuclear Power Plant

ATTACHMENT TO LER 83-024

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Further inspection of the pump motor revealed that the output radial guide bearing was improperly lubricated when the pump was rebuilt by the vendor. As a part of KNPP's preventative maintenance program (PMP) one service water pump motor is sent back to the vendor each year for refurbishing and rebuilding. In the future, the pump motors will be sent to the vendor for refurbishing but will be rebuilt on site. The other three service water pump's lubrication will be checked as a part of the PM Program.

JGT:ksf

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

November 18, 1983

Mr. J. G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence 83-024/03L-0

In accordance with the requirements of the Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence 83-024/03L-0 is being submitted.

Very truly yours,

A handwritten signature in cursive script, appearing to read "C. W. Giesler".

C. W. Giesler
Vice President - Nuclear Power

JGT/jks

Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, DC 20555
Dir, Office of Mgt Info & Program Control
US NRC, Washington, DC 20555
INPO Records Center
Suite 1500, 1100 Circle 75 Parkway
Atlanta, GA 30339
Mr. Robert Nelson, NRC Resident Inspector
RR #1, Box 999, Kewaunee, WI 54216
Mr. S. A. Varga, Chief
US NRC, Washington, DC 20555

NOV 21 1983

IF22 11