

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M I D C C 1 | 2 0 0 - 0 0 0 0 0 0 - 0 0 | 3 4 1 1 1 1 1 | 4 1 1 1 1 1 | 5

CON'T
0 1 | REPORT SOURCE L | 6 0 5 0 0 0 1 3 1 5 | 7 1 0 2 4 8 3 | 8 1 1 2 2 8 3 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 1 2 | DURING POST REFUELING STARTUP, 1-4 STEAM GENERATOR CHANNEL IV PRESSURE TRANSMITTER
0 1 3 | (MPP-242) WAS REMOVED FROM SERVICE TO ALLOW FOR REPAIR OF A STEAM LEAK. THIS CONDITION
0 1 4 | WAS NON-CONSERVATIVE WITH RESPECT TO TECHNICAL SPECIFICATION 3.3.2.1. THE ACTION
0 1 5 | REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. THE CHANNEL WAS
0 1 6 | RETURNED TO SERVICE IN 48 MINUTES.

0 1 7 |
0 1 8 |

0 1 9 |

SYSTEM CODE I B 11	CAUSE CODE E 12	CAUSE SUBCODE B 13	COMPONENT CODE I N S T R U 14	COMP SUBCODE T 15	VALVE SUBCODE Z 16
LER/RO REPORT NUMBER 17	EVENT YEAR 8 3	SEQUENTIAL REPORT NO. 1 1 1	OCCURRENCE CODE 0 3	REPORT TYPE L	REVISION NO. 0
ACTION TAKEN A 13	FUTURE ACTION Z 19	EFFECT ON PLANT Z 20	SHUTDOWN METHOD Z 21	HOURS 0 0 0 0	ATTACHMENT SUBMITTED N 23
				NPRO-4 FORM SUB N 24	PRIME COMP. SUPPLIER A 25
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27			COMPONENT MANUFACTURER F 1 8 0		

1 1 0 | INVESTIGATION FOUND THE STEAM LEAK BETWEEN THE TRANSMITTER AND THE TRANSMITTER
1 1 1 | ISOLATION VALVE. LEAK WAS REPAIRED BY REPLACEMENT OF THE TUBING BETWEEN TRANSMITTER
1 1 2 | AND TRANSMITTER ISOLATION VALVE. TRANSMITTER WAS VERIFIED TO OPERATE CORRECTLY AND
1 1 3 | RETURNED TO SERVICE.

1 1 4 |

FACILITY STATUS C 28	% POWER 0 3 0 29	OTHER STATUS NA 30	METHOD OF DISCOVERY B 31	DISCOVERY DESCRIPTION OPERATOR OBSERVATION 32
ACTIVITY CONTENT Z 33	RELEASED OF RELEASE Z 34	AMOUNT OF ACTIVITY NA 35	LOCATION OF RELEASE NA 36	
PERSONNEL EXPOSURES NUMBER 0 0 0 37	TYPE Z 38	DESCRIPTION NA 39		
PERSONNEL INJURIES NUMBER 0 0 0 40	DESCRIPTION NA 41			
LOSS OF OR DAMAGE TO FACILITY TYPE Z 42	DESCRIPTION NA 43			
PUBLICITY ISSUED N 44	DESCRIPTION NA 45			

8312020298 831122
PDR ADOCK 05000315
S PDR

IE22

NAME OF PREPARER R. A. PALMER

PHONE 616-465-5901

NRC USE ONLY



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

November 22, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications, the following report/s are submitted:

RO 83-111/03L-0

Sincerely,

E L Townley

For W.G. Smith, Jr.
Plant Manager

/cbm

Attachment

cc: John E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E.R. Swanson, RO:III
R.C. Callen, MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee, EPRI
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

NOV 25 1983

IE 27/11