

CP&L

Rec'd
83 NOV 31 P 1
Carolina Power & Light Company

Brunswick Steam Electric Plant

P. O. Box 10429

Southport, NC 28461-0429

November 25, 1983

FILE: B09-13510C

SERIAL: BSEP/83-3848

Mr. James P. O'Reilly, Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

Dear Mr. O'Reilly:

On November 11, 1983, while performing an Engineering evaluation to support the replacement of a Unit No. 2 drywell system PCIV, a conservative determination was made that the drywell equipment drain line (3"), floor drain (3"), and service air header line (1") outside the drywell of each unit were not adequately supported to prevent potential failure inboard of their respective PCIVs during a seismic event. LER 2-83-90 was to have been submitted to your office on November 25, 1983, describing this event. However, the investigation and evaluation of this event is not yet completed. It is anticipated that this report will be submitted by December 9, 1983.

Very truly yours,

C. R. Dietz

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/pms/LETPS1

Enclosure

cc: Mr. R. C. DeYoung
NRC Document Control Desk

8312080081 831125
PDR ADOCK 05000325
S PDR

OFFICIAL COPY

1022
1/0