

## U.S. NUCLEAR REGULATORY COMMISSION

## LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/2/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

/0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/9/ (7) /1/1/0/7/8/3/ (8) /1/1/2/3/8/3/ (9)  
SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On November 7 and November 14, 1983, with Unit 2 in Mode 1 at 100% power, the /  
/0/3/ / inner personnel hatch door was found to have an unacceptable leak rate. This /  
/0/4/ / event is contrary to T.S. 3.6.1.3 and reportable pursuant to T.S. 6.9.1.9.b. /  
/0/5/ / Because the outer personnel door was properly sealed, the health and safety of /  
/0/6/ / the general public were not affected. There are no generic implications /  
/0/7/ / associated with this event. Unit 2 LER 83-057/03L-0 is similar. /  
/0/8/ /

SYSTEM CAUSE CAUSE COMP. VALVE  
CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE

/0/9/ /S/A/ (11) /E/ (12) /X/ (13) /P/E/N/E/T/R/ (14) /A/ (15) /Z/ (16)  
LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION  
REPORT NO. NO.

(17) NUMBER /8/3/ /-/ /0/7/3/ / / /0/3/ /L/ /-/ /0/  
ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT  
TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER

/X/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /N/ (23) /Y/ (24) /A/ (25) /C/3/1/0/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The door seals were dirty from multiple containment entries. The door seals /  
/1/1/ / were cleaned, lubricated and the door was satisfactorily retested. /  
/1/2/ /  
/1/3/ /  
/1/4/ /

FACILITY METHOD OF  
STATUS %POWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION (32)  
/1/5/ /E/ (28) /1/0/0/ (29) / NA / (30) /B/ (31) / Surveillance Test /

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
/1/6/ /Z/ (33) /Z/ (34) / NA / / NA /

PERSONNEL EXPOSURES  
NUMBER TYPE DESCRIPTION (39)  
/1/7/ /0/0/0/ (37) /Z/ (38) / NA /

PERSONNEL INJURIES  
NUMBER DESCRIPTION (41) 8312080092 831123  
/1/8/ /0/0/0/ (40) / NA S PDR ADOCK 05000339 PDR /

LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION  
/1/9/ /Z/ (42) / NA /

PUBLICITY  
ISSUED DESCRIPTION (45) NRC USE ONLY  
/2/0/ /N/ (44) / NA / / / / / / / / / / / / / /

NAME OF PREPARER E. Wayne Harrell PHONE (703) 894-5151

*TEZ*

# Vepco

*Recd*  
83 NOV 31 P 1:05  
VIRGINIA ELECTRIC AND POWER COMPANY  
NORTH ANNA POWER STATION  
P. O. BOX 402  
MINERAL, VIRGINIA 23117

02 DEC 5 49:38

November 23, 1983

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 2900  
Atlanta, Georgia 30303

Serial No. N-83-161  
NO/RST: 11  
Docket No. 50-339  
License No. NPF-7

Dear Mr. O'Reilly:

Pursuant to North Anna Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following License Event Report applicable to North Anna Unit No. 2.

Report No.

Applicable Technical Specifications

LER 83-073/03L-0

T.S. 6.9.1.9.b

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to Safety Evaluation and Control for their review.

Very Truly Yours,

*E. Wayne Harrell*  
E. Wayne Harrell  
Station Manager

Enclosures (3 copies)

cc: Document Control Desk (1 copy)  
016 Phillips Bldg.  
U.S. Nuclear Regulatory Commission  
Washington, D. C. 20555

OFFICIAL COPY

HE 22  
1/1