

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ALJM F 2 2 0 0 - C 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT

01 REPORT SOURCE L 6 0 5 0 0 0 3 6 4 7 1 0 2 5 8 3 8 1 1 2 8 8 3 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 1545 on 10/25/83 during power ascension following refueling, the instrumenta-  
03 tion channels associated with flow transmitters FT-475 (Loop 1 steam flow) and  
04 FT-485 (Loop 2 steam flow) were declared inoperable due to erroneous indication.  
05 Tech. Specs. 3.3.1 and 3.3.2, in part, require these channels to be operable.  
06 Tech. Spec. action statement requirements were met. Health/safety of the public  
07 was not affected.

08

09 I A 11 A 12 C 13 I N S T R U 14 T 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 LER/RO REPORT NUMBER 8 3  
18 ACTION TAKEN H 18 Z 19  
19 FUTURE ACTION Z 20  
20 EFFECT ON PLANT Z 21  
21 SHUTDOWN METHOD Z 22  
22 HOURS 0 0 0 0  
23 ATTACHMENT SUBMITTED Y 23  
24 NPRO-4 FORM SUB N 24  
25 PRIME COMP. SUPPLIER A 25  
26 COMPONENT MANUFACTURER B 0 8 0  
27 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 This event was caused by personnel error and procedural inadequacy. The trans-  
11 mitter power supply links were left open following testing and modification  
12 efforts during the Cycle II-III refueling outage. The power supply links were  
13 closed and following verification of proper indication during performance of  
14 FNP-2-STP-1.0 (Operations Daily and Shift Surveillance (see attachment)

15 F 28 0 2 9 29 NA 30 METHOD OF DISCOVERY A 31 Operator Observation 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 10016 Z 33 Z 34 NA 35 LOCATION OF RELEASE NA 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 10017 0 0 0 37 Z 38 NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 10018 0 0 0 40 NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 10019 Z 42 NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 10020 N 44 NA 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER W. G. Hairston, III

PHONE (205) 899-5156

8312080122 831128  
PDR ADOCK 05000348  
S PDR

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (continued)

Requirements), the FT-475 and FT-485 instrumentation channels were declared operable at 1715 on 10/25/83. This incident was discussed with personnel performing work on these transmitters and procedure modifications have been made to prevent recurrence.