

SUPPLEMENT TO DVR

DVR NO.	STA	UNIT.	YEAR	NO.
D - 12	- 2	- 83	- 127	

PART 1	TITLE OF EVENT	OCCURRED	
	Normally Locked Open Valve Found Locked Closed	9/17/83	1335
	REASON FOR SUPPLEMENTAL REPORT	DATE	TIME
	Further investigation by operations concludes that it is more likely the		
	mistake was not made during performance of DOS 300-7 after a previous scram.		
PART 2			
ACCEPTANCE BY STATION REVIEW	<u>J. Brunner</u>	<u>John M. Almer</u>	
DATE	<u>11/30/83</u>	<u>12/1/83</u>	
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas D. Witt</u>	<u>12/1/83</u>	
	STATION SUPERINTENDENT	DATE	



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

DMB

November 28, 1983

DJS Ltr #83-1138

James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #83-65/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems. This updated report is provided in order to report further investigation regarding the cause of the event and clarify the corrective actions taken.

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

DEC 5 1983

11 IE22