

LICENSEE EVENT REPORT

CONTROL BLOCK:

							(1)
--	--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9						14	15	25										26	30					57	CAT	58
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE								

CON'T

REPORT SOURCE 01 60 61 05 10 10 10 13 11 66 67 70 69 19 26 83 74 88 75 12 01 83 89

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 DURING NORMAL PLANT OPERATION, A SECURITY OFFICER FOUND THE CO₂ SWITCH FOR THE

03 UNIT #2 CD DIESEL GENERATOR ROOM IN THE ISOLATE POSITION WITH NO ONE IN THE ROOM.

04 THIS CONDITION EXISTED FOR 2 HOURS. THIS IS CONTRARY TO THE REQUIREMENTS OF

05 T.S. 3.7.9.3. THE FIRE DETECTION SYSTEM WAS OPERABLE DURING THIS PERIOD. PUBLIC

06 HEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURRENCES WERE REPORTED VIA

07 REPORTS 315/82-037, 044, 045, 049, 068, 081, 082, 108, 316/82-054, 058, 062, 074,

08 076, 084. 315/83-030, 048, 060, 316/83-022, 028, 034.

SYSTEM CODE A B		CAUSE CODE A		CAUSE SUBCODE X		COMPONENT CODE Z Z Z Z Z Z						COMP. SUBCODE Z		VALVE SUBCODE Z													
9 10		11 12		13 14		15 16 17 18 19 20						21 22		23 24													
EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 9 3		OCCURRENCE CODE 0 1		REPORT TYPE X		REVISION NO. 1		ACTION TAKEN X		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER Z		COMPONENT MANUFACTURER Z 9 9 9	
21 22		23 24		25 26		27 28		29 30		31 32		33 34		35 36		37 38		39 40		41 42		43 44		45 46		47 48	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | FURTHER INVESTIGATION INTO THE EVENT HAS FAILED TO DETERMINE WHEN AND BY WHOM THE

1 1 | CO2 ISOLATION SWITCH WAS PLACED IN THE "ISOLATE" POSITION. APPROPRIATE ADMIN-

1 2 | ISTRATIVE ACTION HAS BEEN TAKEN WITH THE SECURITY OFFICERS WHO WERE DERELICT IN

1 3 | THEIR DUTIES AS SWITCH WATCHERS.

1 4 7 8 9
 FACILITY STATUS 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 1 5 0 E 10 0 29 NA 30
 METHOD OF DISCOVERY 31 32
 B 31 SECURITY OFFICER OBSERVATION 32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 34 NA

AMOUNT OF ACTIVITY (35)

NA LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
0	0	0	40 NA

TE22

8 9 11 12
LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) NA
8312090246 831201
PDR ADOCK 05000316
S PDR

8 9 10
PUBLICITY
ISSUED DESCRIPTION (45)
2 0 IN (44) NA

NRC USE ONLY

NAME OF PREPARER P. D. RICHARD

PHONE 616-465-5901

NRC USE ONLY

100

DMB



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

December 1, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical
Specifications, the following report/s are submitted:

RO 83-093/01X-1

Sincerely,

W. G. Smith, Jr.
W.G. Smith, Jr.
Plant Manager

/cbm

Attachment

cc: John E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E.R. Swanson, RO:III
R.C. Callen, MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee, EPRI
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

DEC - 5 1983

11 IE21