

EXPIRES 4-30-62

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE (704) 373-7432

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

DEC 22 ALL: 09
December 9, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Unit 2
Docket No. 70
LER/RO-370/83-73

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-370/83-73. This report concerns T.S. 3.3.2, "The Engineered Safety Features Actuation System (ESFAS) Instrumentation Channels and Interlocks Shown in Table 3.3-3 Shall Be Operable...". This incident was considered to be of no significance with respect to the health and safety of the public.

Investigation to determine the cause of the improper wire disconnection is continuing. A followup report will be submitted if/when cause is determined.

Very truly yours,

H.B. Tucker

Hal B. Tucker

PBN:jfw
Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY

LEZ2
1/1