

## LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y N M P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 2 2 0 7 1 1 2 8 8 3 8 1 2 0 7 8 3 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operations the Fuel Zone Water Level Measuring System (Accurex) was found  
0 3 in a "System Idle" condition for Channel 11(A) at the time that the surveillance pro-  
0 4 cedure N1-ISP-36-ICC was to be performed. Consequences were minimal since corrective  
0 5 action was taken immediately, the redundant FZWLMS (Accurex) Channel 12(A) was operable  
0 6 and the system only activates during a severe accident. LER 83-36 reported a similar  
0 7 occurrence.

0 8  
7 8 9 80

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
7 8 9 10 11 12 13 18 19 20  
Z Z X Z Z Z Z Z Y Z  
(11) (12) (13) (14) (15) (16)  
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
21 22 23 24 26 27 28 29 30 31 32  
8 3 0 4 3 0 3 L 0  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
33 34 35 36 37 40 41 42 43 44 47  
F X Z Z 0 0 0 0 X N Z Z 9 9 9  
(18) (19) (20) (21) (22) (23) (24) (25) (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Immediate corrective actions taken were pushing the "start" button on the Accurex and  
1 1 running the N1-ISP-36-ICC Surveillance Procedure. The Accurex was then declared  
1 2 operable. The cause of this event is still not known. Future actions being taken  
1 3 include further investigation into the reasons for the idle condition of the Accurex  
1 4 on Channel 11(A) and possible actions to alleviate this type of occurrence in the future.

7 8 9 (See attached sheet) 80  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
1 5 E 1 0 0 NA B INSPECTION  
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
7 8 9 10 11 44 45 80  
Z Z NA NA

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
7 8 9 11 12 13 80  
0 0 0 Z NA

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION  
7 8 9 11 12 80  
0 0 0 NA

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
7 8 9 10 80  
Z NA

2 0 PUBLICITY ISSUED DESCRIPTION  
7 8 9 10 80  
N NA

NAME OF PREPARER A.R. SCHWEDT

PHONE (315) 349-2616

8401030265 831209  
PDR ADOCK 05000220  
S PDR

NRC USE ONLY

LICENSEE EVENT REPORT 83-43

(continued)

Cause Description and Corrective Actions

Also the additional frequency of surveillance on the Accurex, initiated as a result of L.E.R. #36, has been maintained, and will continue until this problem is resolved.