

CONTROL BLOCK: 

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1																
7	8																

REPORT SOURCE

L	6	0	5	0	0	0	3	1	5	7	1	2	1	2	8	3	8	0	1	0	4	8	4	9		
60	61	DOCKET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

0 2 DURING STEAM GENERATOR CREVICE FLUSHING WITH THE RCS IN HOT SHUTDOWN, WHILE ON A

0 3 ROUTINE TOUR, FOUR ICE CONDENSER INTERMEDIATE DECK DOORS WERE FOUND FROZEN SHUT

0 4 WHICH WAS NONCONSERVATIVE WITH RESPECT TO T.S. 3.6.5.3. THE DOORS WERE IMMEDIATELY

0 5 FREED SO THAT THEY COULD OPEN IF REQUIRED. THE REMAINING INTERMEDIATE DECK DOORS

0 6 WERE OPERABLE. PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS SIMILAR

0 7 OCCURRENCES INCLUDE: 79-036, 79-045, 79-060, 80-010, 80-021, 80-024, 82-109,

0 8 82-110, 83-068 AND FOR DOCKET 316, 81-029 AND 81-038.

09		SYSTEM CODE S B		11	CAUSE CODE E		12	CAUSE SUBCODE B						13	COMPONENT CODE X X X X X X X						14	COMP. SUBCODE Z		15	VALVE SUBCODE Z		16																																																			
7	8	9	10		11	12		13	14	15	16	17	18	19	20																																																															
17		LER/RO REPORT NUMBER		EVENT YEAR 8 3		22	SEQUENTIAL REPORT NO. 1 2 2		24	OCCURRENCE CODE 0 3		28	REPORT TYPE L		30	REVISION NO. 0		32	ACTION TAKEN B		18	FUTURE ACTION Z		19	EFFECT ON PLANT Z		20	SHUTDOWN METHOD Z		21	HOURS 0 0 0 0		22	ATTACHMENT SUBMITTED N		23	NPRD-4 FORM SUB N		24	PRIME COMP. SUPPLIER A		25	COMPONENT MANUFACTURER Z 9 9 9		26																																	
21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99

1 0 ICE ACCUMULATION AROUND THE DOORS RESULTED IN THE DOORS BEING FROZEN. THE ICE

1 1 WAS REMOVED. INVESTIGATION REVEALED THAT THE ICE BUILDUP RESULTED FROM LEAKING

1 2 DRAIN LINES ON THE ICE CONDENSER AIR HANDLERS 4-2A, 4-4A AND 1-5B. THE LEAKING

1 3 DRAIN LINES WERE REPAIRED.

1	4											80						
7	8	9											80					
FACILITY STATUS			% POWER			OTHER STATUS			(30)	METHOD OF DISCOVERY			DISCOVERY DESCRIPTION			(32)	80	
1	5	C	(78)	0	0	0	(29)	NA		B	(31)	OPERATOR OBSERVATION						80
7	8	9	ACTIVITY CONTENT RELEASED			AMOUNT OF ACTIVITY			(35)	LOCATION OF RELEASE					(36)	80		
1	6	Z	(33)	Z	(34)	NA				NA						80		
7	8	9	PERSONNEL EXPOSURES													80		
NUMBER			TYPE			DESCRIPTION			(39)							80		
1	7	0	0	0	0	(37)	Z	(38)	NA							80		
7	8	9	PERSONNEL INJURIES													80		
NUMBER			DESCRIPTION			(41)									80			
1	K	0	0	0	0	(40)	NA									80		
7	8	9	LOSS OF OR DAMAGE TO FACILITY			(43)									80			
TYPE			DESCRIPTION			(42)			NA						80			
1	9	Z	(47)													80		
7	8	9	PUBLICITY			(45)									80			
ISSUED			DESCRIPTION			(44)			NA						80			
2	0	N	(44)													80		
7	8	9													80			
										NRC USE ONLY								80
										<div style="display: flex; justify-content: space-between;"> <span>68</span> <span>69</span> </div>								80

W. J. FLAGA

PHONE 616-465-5901

DMB



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

January 4, 1984

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,  
the following report/s are submitted:

RO 83-122/03L-0

Sincerely,

W.G. Smith, Jr.  
Plant Manager

/chm

cc: J.E. Dolan  
M.P. Alexich  
R.F. Kroeger  
H. Brugger  
E. Swanson  
R.C. Callen MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee  
INPO  
PNBRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (30 copies)  
Dir., MIPC (3 copies)

JAN 9 1984

IE2211