

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT
/0/1/ REPORT /L/ (6) /0/5/0/0/0/3/3/8/ (7) /1/2/0/2/8/3/ (8) /1/2/2/1/8/3/ (9)
SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

/0/2/ / On December 2, 1983, with Units 1 and 2 at 100 percent power, the fire door /
/0/3/ / between the Clean Change Room and the Auxiliary Building would not latch auto- /
/0/4/ / matically. Since a fire watch was established within one hour and the Auxiliary /
/0/5/ / Building fire protection system is monitored remotely from the Control Room, the /
/0/6/ / health and safety of the general public were not affected. This event is within /
/0/7/ / the Action Statement of T.S. 3.7.15 and reportable pursuant to T.S. 6.9.1.9.b. /
/0/8/ /

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
/0/9/ /A/E/ (11)	/E/ (12)	/E/ (13)	/X/X/X/X/X/X/ (14)	/Z/ (15)	/Z/ (16)
LER/RO REPORT NUMBER	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.

(17) /8/3/ /-/ /0/8/4/ / / /0/3/ /L/ /-/ /0/
ACTION FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT
TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
/B/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /0/0/0/0/ (22) /N/ (23) /N/ (24) /A/ (25) /F/0/7/5/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / Several screws securing the hinges to the door had worked loose and four screws /
/1/1/ / were missing which allowed the door to become misaligned. The screws were /
/1/2/ / tightened and missing screws were replaced. The door was aligned and verified to /
/1/3/ / latch automatically within 5 hours. There are no generic implications associated /
/1/4/ / with this event. /

FACILITY STATUS	%POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
/1/5/ /E/ (28)	/1/0/0/ (29)	/ NA / (30)	/A/ (31)	/ Operator Observation /
ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)	
/1/6/ /Z/ (33)	/Z/ (34)	/ NA /	/ NA /	/
PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION (39)		
/1/7/ /0/0/0/ (37)	/Z/ (38)	/ NA /		/
PERSONNEL INJURIES NUMBER	DESCRIPTION (41)			
/1/8/ /0/0/0/ (40)	/ NA /			/
LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION (43)			
/1/9/ /Z/ (42)	/ NA /			/
PUBLICITY ISSUED	DESCRIPTION (45)			
/2/0/ /N/ (44)	/ NA /			

NAME OF PREPARER E. Wayne Harrell PHONE (703) 894-5151

8401040549 831221
PDR ADDCK 05000338
S PDR

IE22



VIRGINIA ELECTRIC AND POWER COMPANY

NORTH ANNA POWER STATION

P. O. BOX 402

MINERAL, VIRGINIA 23117

December 21, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303

Serial No. N-83-173
NO/DAH: 11
Docket No. 50-338
License No. NPF-4

Dear Mr. O'Reilly:

Pursuant to North Anna Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following License Event Report applicable to North Anna Unit No. 1.

Report No.


Applicable Technical Specifications

LER 83-084/03L-0

T.S. 6.9.1.9.b

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be forwarded to Safety Evaluation and Control for their review.

Very Truly Yours



E. Wayne Harrell
Station Manager

Enclosures (3 copies)

cc: Document Control Desk (1 copy)
016 Phillips Bldg.
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

11
OFFICIAL COPY
1E 22