



POWER AUTHORITY OF THE STATE OF NEW YORK  
JAMES A. FITZPATRICK NUCLEAR POWER PLANT


DOCKET NO. 50-333

ATTACHMENT TO LER 83-061

PAGE 2 of 2

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (continued)

replaced when parts become available. All RHR service water pumps are routinely monitored for vibration.



December 22, 1983  
JAFP 83-1253

Dr. Thomas Murley  
Regional Administrator  
United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

REFERENCE: DOCKET NO. 50-333  
LICENSEE EVENT REPORT: 83-061/03L-0

Dear Dr. Murley:

We have enclosed the referenced Licensee Event Report in accordance with Section 2.2 of Technical Specifications and USNRC Regulatory Guide 1.16.

If there are any questions concerning this report, please contact Mr. Richard Wiese at 315-342-3840, extension 222.

Very truly yours,

by dir. *R. McNeill*  
CORBIN A. McNEILL, JR.  
RESIDENT MANAGER

CAM:DR:nan  
Enclosure

CC: USNRC Document Control Desk (1)  
INPO Records Center, Atlanta, Ga. (1)  
Internal Power Authority Distribution  
NRC Resident Inspector  
Document Control Center  
LER/OR File

IE22  
11