


**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

December 20, 1983

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

This is to confirm a telephone report made by our Assistant Plant Manager, Mr. E.L. Townley, to Mr. D.C. Boyd, NRC Region III, at 1503 hours on December 20, 1983, at which time we reported that during the investigation of an instrument failure of the Unit 1 Vent Stack Monitoring Instrumentation which occurred on November 25, 1983, it was discovered that the Action Statement in Technical Specification Table 3.3-13, 3b and c was not met in that samples required for weekly analysis were not continuously collected with auxiliary sampling equipment. Mr. E.R. Swanson, NRC Senior Resident Inspector, was also advised of this occurrence on December 20, 1983, at 1455 hours.

As required by Technical Specification 6.9.1.12 a followup report will be submitted within fourteen days.

Sincerely,

*E. L. Townley*

for W.G. Smith, Jr.  
Plant Manager

/bab

8401050441 831220  
PDR ADOCK 05000315  
S PDR

Attachment

cc: John E. Dolan  
M.P. Alexich  
R.F. Kroeger  
H. Brugger  
E.R. Swanson, RO:III  
R.C. Callen, MPSC  
G. Charnoff, Esq.  
J.M. Hennigan

INPO  
Dir., IE (40 copies)  
Dir., MIPC (4 copies)  
PNSRC  
J.F. Stietzel  
E.L. Townley  
K.R. Baker  
R.O. Bruggee, EPRI

DEC 23 1983  
IE 221/0