

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

January 5, 1979

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Recirculation Discharge Bypass Valve Failure - Revised Report

A revised Licensee Event Report for this occurrence is printed on the back of this letter. Enclosed are three copies.

The original report contained a typographical error in the valve identification number. The correct valve number is MO-2-54A.

Yours very truly,

David Musolf FOR

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/deh

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
MPCA

Attn: J W Ferman

REGULATORY DOCKET FILE COPY

7901090242

-over-

1002
5/11