

Georgia Power Company
40 Inverness Center Parkway
Post Office Box 1295
Birmingham, Alabama 35201
Telephone 205 877-7279

J. T. Beckham, Jr.
Vice President - Nuclear
Hatch Project



May 1, 1995

Docket Nos. 50-321
50-366

HL-4838

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Edwin I. Hatch Nuclear Plant
Safeguards Event Log


Gentlemen:

In accordance with the requirements of 10 CFR 73.71(c)(2), Georgia Power Company is providing a copy of the safeguards event log for the Edwin I. Hatch Nuclear Plant for the first quarter of 1995.

This log has been reviewed and determined not to contain safeguards information requiring protection. Therefore, this log can be placed in the public document room.

Should you have any questions in this regard, please contact this office.

Sincerely,



J. T. Beckham, Jr.

JKB/eb

Enclosure: Safeguards Event Log

cc: Georgia Power Company
Mr. H. L. Sumner, Nuclear Plant - General Manager
NORMS

U.S. Nuclear Regulatory Commission, Washington, D.C.
Mr. K. Jabbour, Licensing Project Manager - Hatch

U.S. Nuclear Regulatory Commission, Washington, D.C.
Mr. S. D. Ebnetter, Regional Administrator
Mr. B. L. Holbrook, Senior Resident Inspector - Hatch

9505090105 950501
PDR ADOCK 05000321
F PDR

5002

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 1

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-001	1/1/95	00:32	1/1/95	01:35	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-002	1/2/95	01:30	1/2/95	05:00	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-003	1/2/95	14:39	1/2/95	17:30	ALARM WITH NO RESET ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-004	1/4/95	21:27	1/4/95	23:30	PERSONNEL IN CLEAR ZONE DURING SECURITY DRILL WITHOUT ARMED OFFICER PRESENT.	ARMED OFFICER DISPATCHED TO ZONE UNTIL TERMINATION OF DRILL.
95-1-005	1/5/95	18:02	1/5/95	18:10	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 2

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-006	1/6/95	13:12	1/6/95	18:00	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-007	1/6/95	18:03	1/6/95	18:03	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-008	1/6/95	19:37	1/6/95	22:45	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-009	1/6/95	22:42	1/6/95	23:03	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-010	1/7/95	01:50	1/7/95	04:55	ELECTRONIC FAILURE ON SECURITY CAMERA.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 3

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-011	1/7/95	20:08	1/8/95	05:30	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-012	1/10/95	08:25	1/10/95	11:30	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-013	1/10/95	18:52	1/10/95	21:50	PROTECTED AREA GATE NOT PROPERLY SECURED.	COMPENSATORY MEASURES TAKEN.
95-1-014	1/10/95	22:49	1/10/95	23:30	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-015	1/11/95	10:45	1/11/95	13:30	AUDIT OF CONTRACTORS BI PROGRAM REVEALED ONE INCOMPLETE BACKGROUND.	ACCESS REVOKED AND FULL BI COMPLETED SATISFACTORILY.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 4

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-016	1/11/95	23:35	1/12/95	04:35	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-017	1/12/95	06:45	1/12/95	08:15	PERSONNEL EXITED PROTECTED AREA WITH VITAL AREA DOOR KEY AT 15:30, 01/11/95.	KEY RETURNED 06:45, 01/12/95. KEY CORE CHANGED OUT 06:52. ALARM HISTORY REVEALED NO USAGE
95-1-018	1/12/95	10:41	1/12/95	12:00	POOR VISIBILITY ON PERIMETER CAMERA.	COMPENSATORY MEASURES TAKEN.
95-1-019	1/12/95	21:30	1/12/95	23:30	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-020	1/13/95	03:12	1/13/95	04:15	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 5

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-021	1/13/95	03:44	1/13/95	05:15	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-022	1/13/95	12:11	1/13/95	14:00	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-023	1/13/95	21:38	1/14/95	02:20	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-024	1/13/95	22:28	1/14/95	02:40	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-025	1/14/95	02:34	1/14/95	02:55	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 6

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-026	1/14/95	05:30	1/14/95	22:00	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-027	1/14/95	06:55	1/14/95	13:40	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-028	1/14/95	14:25	1/14/95	17:37	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-029	1/15/95	05:17	1/15/95	05:31	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-030	1/15/95	06:06	1/15/95	06:15	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 7

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-031	1/15/95	07:40	1/15/95	11:35	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-032	1/15/95	18:42	1/15/95	22:30	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-033	1/15/95	21:55	1/15/95	22:40	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-034	1/17/95	02:55	1/17/95	03:35	LOSS OF ALARM CAPABILITY ON PROTECTED AREA GATE BMS.	COMPENSATORY MEASURES TAKEN. REPAIRS INITIATED.
95-1-035	1/17/95	05:50	1/17/95	06:21	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 8

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-036	1/18/95	00:07	1/18/95	05:08	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-037	1/19/95	04:02	1/19/95	04:20	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-038	1/19/95	04:22	1/19/95	04:35	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-039	1/19/95	05:01	1/19/95	05:25	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-040	1/19/95	08:50	1/19/95	09:30	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 9

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-041	1/19/95	13:15	1/19/95	14:55	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-042	1/23/95	07:10	1/23/95	11:15	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-043	1/24/95	02:05	1/24/95	02:30	DOOR STRIKE FAILURE ON VITAL AREA DOOR.	COMPENSATORY MEASURES TAKEN. REPAIR INITIATED.
95-1-044	1/25/95	20:44	1/25/95	22:55	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-045	1/27/95	01:38	1/27/95	03:05	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 10

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-046	1/27/95	09:05	1/27/95	10:57	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-047	1/27/95	22:28	1/28/95	01:50	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-048	1/28/95	01:20	1/28/95	02:20	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-049	1/28/95	01:35	1/28/95	02:45	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-050	1/28/95	08:35	1/28/95	12:40	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 11

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-051	1/28/95	11:35	1/28/95	13:05	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-052	1/28/95	19:36	1/28/95	22:15	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-053	1/28/95	22:55	1/28/95	23:15	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-054	1/28/95	23:30	1/28/95	23:50	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-055	1/29/95	03:46	1/29/95	04:10	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 12

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-056	1/29/95	19:30	1/30/95	00:15	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-057	1/29/95	21:13	1/30/95	00:50	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-058	1/30/95	05:23	1/30/95	06:15	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-059	1/30/95	01:54	1/30/95	02:25	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-060	2/3/95	10:00	2/3/95	15:00	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 13

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-061	2/3/95	20:10	2/3/95	23:30	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-062	2/4/95	09:01	2/4/95	10:04	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-063	2/4/95	01:02	2/4/95	03:24	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-064	2/6/95	01:22	2/6/95	04:20	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-065	2/6/95	04:17	2/6/95	04:40	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 14

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-066	2/6/95	05:20	2/6/95	05:20	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-067	2/6/95	10:35	2/6/95	13:00	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-068	2/6/95	16:00	2/7/95	14:30	AUDIT IDENTIFIED SAFEGUARDS DEVELOPMENT ON LAN WITH OFFSITE NODE.	NO INFORMATION WAS BEING STORED ON THE LAN. PRACTICE DISCONTINUED AS CONSERVATIVE
95-1-069	2/7/95	19:10	2/7/95	23:55	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-070	2/8/95	09:55	2/8/95	16:00	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 15

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-071	2/8/95	19:08	2/8/95	23:00	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-072	2/9/95	00:32	2/9/95	02:50	FREQUENT ALARM ON DOOR.	COMPENSATORY MEASURES TAKEN.
95-1-073	2/9/95	02:30	2/9/95	03:06	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-074	2/10/95	05:40	2/10/95	05:52	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-075	2/10/95	07:00	2/10/95	07:50	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 16

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-076	2/10/95	11:00	2/11/95	03:30	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-077	2/11/95	02:03	2/11/95	04:20	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-078	2/11/95	02:45	2/11/95	04:16	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-079	2/11/95	10:05	2/11/95	15:40	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-080	2/11/95	18:17	2/11/95	18:20	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 17

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-081	2/12/95	01:27	2/12/95	06:00	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-082	2/13/95	22:15	2/13/95	23:55	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-083	2/14/95	10:52	2/14/95	17:00	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-084	2/14/95	13:50	2/14/95	15:00	IMPROPERLY SECURED VEHICLE.	VEHICLE SECURED UPON DISCOVERY. DRIVER ADVISED OF PROPER PROCEDURE.
95-1-085	2/14/95	21:04	2/14/95	23:25	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 18

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-086	2/15/95	08:30	2/15/95	13:59	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-087	2/15/95	11:57	2/15/95	14:05	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-088	2/17/95	06:54	2/17/95	16:30	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-089	2/17/95	11:21	2/17/95	14:00	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-090	2/17/95	11:50	2/17/95	14:40	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 19

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-091	2/17/95	12:02	2/17/95	14:30	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-092	2/17/95	20:44	2/17/95	21:50	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-093	2/17/95	21:15	2/17/95	22:05	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-094	2/18/95	01:15	2/18/95	02:20	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-095	2/18/95	17:50	2/18/95	18:10	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 20

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-096	2/18/95	18:57	2/18/95	21:70	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-097	2/18/95	21:20	2/18/95	21:35	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-098	2/19/95	01:02	2/19/95	02:45	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-099	2/19/95	01:19	2/19/95	02:50	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-100	2/19/95	18:32	2/20/95	02:50	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 21

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-101	2/19/95	20:58	2/20/95	03:10	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-102	2/20/95	05:40	2/20/95	06:04	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-103	2/21/95	10:55	2/21/95	11:07	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-104	2/25/95	06:50	2/25/95	14:30	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-105	2/26/95	18:44	2/26/95	19:35	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 22

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-106	2/27/95	01:14	2/27/95	02:00	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-107	2/27/95	04:37	2/27/95	05:10	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-108	2/27/95	11:22	2/27/95	18:00	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-109	2/27/95	18:38	2/27/95	22:25	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-110	2/28/95	16:45	2/20/95	17:55	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 23

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-111	2/28/95	20:11	2/28/95	20:45	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-112	3/1/95	01:18	3/1/95	05:02	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-113	3/1/95	14:20	3/1/95	15:20	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-114	3/1/95	21:47	3/1/95	22:00	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-115	3/2/95	15:00	3/2/95	15:25	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 24

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-116	3/2/95	23:31	3/3/95	01:30	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-117	3/3/95	18:45	3/4/95	00:24	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-118	3/3/95	20:15	3/4/95	00:30	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-119	3/4/95	18:42	3/4/95	20:24	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-120	3/5/95	16:40	3/5/95	16:50	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 25

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-121	3/5/95	18:00	3/5/95	18:11	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-122	3/5/95	23:03	3/5/95	23:35	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-123	3/6/95	20:00	3/6/95	20:15	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-124	3/7/95	01:01	3/7/95	01:35	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-125	3/7/95	03:49	3/7/95	04:05	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 26

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-126	3/7/95	18:00	3/7/95	18:05	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-127	3/7/95	19:09	3/7/95	20:10	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-128	3/7/95	23:34	3/8/95	00:15	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-129	3/8/95	04:52	3/8/95	05:15	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-130	3/8/95	13:20	3/5/89	14:23	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 27

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-131	3/8/95	22:10	3/8/95	22:30	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-132	3/9/95	23:11	3/9/95	23:25	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-133	3/10/95	21:07	3/10/95	21:30	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-134	3/11/95	19:08	3/11/95	21:15	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-135	3/12/95	18:52	3/12/95	19:50	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 28

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-136	3/13/95	13:25	3/13/95	14:55	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-137	3/14/95	04:30	3/14/95	04:40	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-138	3/14/95	10:00	3/14/95	15:08	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-139	3/15/95	11:05	3/15/95	16:45	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-140	3/16/95	04:48	3/16/95	05:25	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 29

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-141	3/16/95	05:02	3/16/95	06:00	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-142	3/17/95	18:57	3/17/95	23:25	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-143	3/18/95	09:10	3/18/95	11:25	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-144	3/18/95	14:45	3/18/95	14:55	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-145	3/18/95	14:52	3/18/95	16:00	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch

Quarterly Safeguards Event Log

Page 30

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-146	3/18/95	15:24	3/18/95	16:00	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-147	3/19/95	01:00	3/19/95	01:23	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-148	3/19/95	22:56	3/20/95	05:45	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-149	3/20/95	21:15	3/20/95	22:00	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-150	3/24/95	19:41	3/24/95	20:15	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 31

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-151	3/25/95	00:46	3/25/95	01:30	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-152	3/25/95	06:17	3/25/95	06:25	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.
95-1-153	3/25/95	20:02	3/25/95	22:20	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-154	3/26/95	20:05	3/26/95	21:00	FREQUENT ALARMS ON PERIMETER ZONE.	COMPENSATORY MEASURES TAKEN.
95-1-155	3/26/95	06:50	3/26/95	16:55	POOR VISIBILITY ON PERIMETER CAMERAS.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.

Plant E. I. Hatch
Quarterly Safeguards Event Log

Page 32

Log #	Event Date	Event Time	Log Date	Log Time	Event Summary	Report Summary
95-1-156	3/31/95	05:14	3/31/95	05:25	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-157	3/31/95	05:34	3/31/95	05:45	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.
95-1-158	3/31/95	19:14	3/31/95	23:59	FREQUENT ALARMS ON PERIMETER ZONES.	COMPENSATORY MEASURES TAKEN.

Weather conditions and site cooling tower configuration contributes to the rate of alarms and visibility entries, which are often higher than industry averages.