



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

January 15, 1979

2-019-11

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Reportable Occurrence Report  
Nos. 50-368/78-24, 50-368/78-25,  
and 50-368/78-26  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One-Unit 2 Technical Specifications 6.9.1.9, we have attached the subject reports concerning the failure to perform a surveillance test on Emergency Escape Hatch and Personnel Hatch (50-368/78-24); inoperability of CEAC #1 (50-368/78-25); and inoperability of an Emergency Feedwater train (50-368/78-26).

Two of these Reportable Occurrence Reports are being submitted late with the concurrence of the on-site Inspector.

Very truly yours,

Daniel H. Williams  
Manager, Licensing

DHW:REI:ce  
Attachments

cc: Mr. John G. Davis, Acting Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Norman M. Haller, Director  
Office of Management Information  
& Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

REGULATORY DOCKET FILE COPY

A002  
S  
1/1

7901300064