

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

JOSEPH W. GALLAGHER
MANAGER
ELECTRIC PRODUCTION DEPARTMENT

(215) 841-5003

January 26, 1983

Re: Docket Nos. 50-277
50-278

IE Bulletin 82-04

Mr. R. C. Haynes, Administrator
Region I
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. Haynes:

Your letter dated December 3, 1982, forwarded IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" which identified deficiencies in containment electrical penetrations supplied by Bunker Ramo utilizing the hard epoxy module design. Our review has determined that no Bunker Ramo electrical penetrations are installed or planned to be installed in safety-related systems at Peach Bottom. Therefore, in accordance with the Bulletin, no further action is required.

The following information is provided to help the NRC in evaluating the cost of implementing this bulletin:

- 1) Utility staff time to perform the requested inspection - five man hours.

8302030105 830126
PDR ADQCK 05000277
G PDR

IE 11

- 2) Radiation exposure attributed to requested inspection - none.
- 3) Utility staff time to prepare the written response - three man hours.

If there are any further questions, do not hesitate to contact us.

Very truly yours,

JW Gallagher

cc: Site Inspector
Peach Bottom