

## LICENSEE EVENT REPORT

Update Report - Previous Report  
Date - 6-25-80

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 GA E I H 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T

REPORT  
SOURCE

01 L 6 0 5 0 0 0 0 3 2 1 7 0 6 1 2 8 0 8 0 1 2 5 8 3 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With Unit 1 in cold shutdown, an investigation was begun to determine  
03 the cause of pavement deflection which occurred beneath a crane outrig-  
04 ger pad at the intake structure. The investigation revealed a settling  
05 of fill material under the service water and RHR service water lines.  
06 Remedial action was required in order to comply with FSAR compaction  
07 requirements. There were no effects on public health and safety due to  
08 this event. This is not a repetitive occurrence.

SYSTEM  
CODECAUSE  
CODECAUSE  
SUBCODE

COMPONENT CODE

COMP.  
SUBCODEVALVE  
SUBCODE

09 Z Z 11 X 12 X 13 Z Z Z Z Z Z 14 X 15 X 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

LER/RO  
REPORT  
NUMBER

EVENT YEAR

SEQUENTIAL  
REPORT NO.OCCURRENCE  
CODER. PORT  
TYPEREVISION  
NO.ACTION  
TAKENFUTURE  
ACTIONEFFECT  
ON PLANTSHUTDOWN  
METHOD

HOURS

ATTACHMENT  
SUBMITTEDNPRD-4  
FORM SUB.PRIME COMP.  
SUPPLIERCOMPONENT  
MANUFACTURER

17 8 0 26 0 1 31 1  
33 X 34 X 35 Z 36 Z 37 0 38 0 39 0 40 0 41 N 42 N 43 Z 44 Z 45 9 46 9 47 9 48 9 49 9 50 9 51 9 52 9 53 9 54 9 55 9 56 9 57 9 58 9 59 9 60 9 61 9 62 9 63 9 64 9 65 9 66 9 67 9 68 9 69 9 70 9 71 9 72 9 73 9 74 9 75 9 76 9 77 9 78 9 79 9 80 9 81 9 82 9 83 9 84 9 85 9 86 9 87 9 88 9 89 9 90 9 91 9 92 9 93 9 94 9 95 9 96 9 97 9 98 9 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause was determined to be improper compaction of a localized area  
11 immediately in front of the intake structure. The improperly compacted  
12 backfill was replaced with a proprietary backfill, "K-crete" per a  
13 design change request. Work was started 10-17-80 and finished 8-28-81.

14  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

FACILITY  
STATUS

% POWER

OTHER STATUS

METHOD OF  
DISCOVERY

DISCOVERY DESCRIPTION (32)

15 G 28 0 0 0 29 NA C 31 Geo Technical Investigation  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTIVITY  
RELEASED

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

16 Z 33 Z 34 NA NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL EXPOSURES

NUMBER

TYPE

DESCRIPTION (39)

17 0 0 0 37 Z 38 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL INJURIES

NUMBER

DESCRIPTION (41)

18 0 0 0 40 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

LOSS OF OR DAMAGE TO FACILITY  
TYPE DESCRIPTION (43)

19 Z 42 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PUBLCITY

ISSUED

DESCRIPTION (45)

20 N 44 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

8302030294 830125  
PDR ADOCK 05000321  
S PDR

NRC USE ONLY

NAME OF PREPARER H. L. Sumner - Supt. Plt. Eng. Serv.

PHONE: 912-367-7851