

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	S	G	G	S	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	---

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0	1	L	6	0	5	0	0	0	4	1	6	7	0	1	0	1	8	3	8	0	1	3	1	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On January 1, 1983, with the plant in cold shutdown, Shutdown Cooling Loop A was declared inoperable in order to replace a discharge check valve. Both shutdown cooling loops are required to be operable by T.S.3.4.9.2. This event had no effect on the health and safety of the public and did not constitute a threat to plant safety. The event is reported pursuant to T.S.6.9.1.13.b.

0	9	C	F	11	X	12	Z	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16	17	8	3	18	0	0	9	19	0	3	20	L	21	0	22	0	3	23	N	24	N	25	Z	26	9	9	9	9	27
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	----	---	---	----	---	---	---	----	---	---	----	---	----	---	----	---	---	----	---	----	---	----	---	----	---	---	---	---	----

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 19 VALVE SUBCODE 20 LER RO REPORT NUMBER 21 EVENT YEAR 22 SEQUENTIAL REPORT NO. 23 OCCURRENCE CODE 24 REPORT TYPE 25 REVISION NO. 26 ACTION TAKEN 27 FUTURE ACTION 28 EFFECT ON PLANT 29 SHUTDOWN METHOD 30 HOURS 31 ATTACHMENT SUBMITTED 32 NPRD-4 FORM SUB. 33 PRIME COMP. SUPPLIER 34 COMPONENT MANUFACTURER 35

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Shutdown Cooling Loop A was tagged out in order to replace the discharge check valve for the RHR A jockey pump. An LCO was initiated and a CRD pump was started to provide alternate decay heat removal in accordance with T.S.3.4.9.2. The jockey pump work was completed and the system was returned to service on January 4, 1983. This is a final report.

1	5	G	28	0	0	0	29	NA	30	A	31	Planned Action	32
---	---	---	----	---	---	---	----	----	----	---	----	----------------	----

FACILITY STATUS 9 10 % POWER 11 12 OTHER STATUS 13 METHOD OF DISCOVERY 14 DISCOVERY DESCRIPTION 15

1	6	Z	33	Z	34	NA	35	NA	36
---	---	---	----	---	----	----	----	----	----

ACTIVITY CONTENT 16 17 RELEASED OF RELEASE 18 19 AMOUNT OF ACTIVITY 20 21 LOCATION OF RELEASE 22

1	7	0	0	0	37	Z	38	NA	39
---	---	---	---	---	----	---	----	----	----

PERSONNEL EXPOSURES NUMBER 17 18 TYPE 19 DESCRIPTION 20

1	8	0	0	0	40	NA	41
---	---	---	---	---	----	----	----

PERSONNEL INJURIES NUMBER 18 19 DESCRIPTION 20

1	9	Z	42	NA	43
---	---	---	----	----	----

LOSS OF OR DAMAGE TO FACILITY TYPE 19 DESCRIPTION 20

2	0	N	44	8302030307 830131 PDR ADOCK 05000416 S PDR	45
---	---	---	----	--	----

PUBLICITY ISSUED DESCRIPTION 20 21

NRC USE ONLY