



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

October 19, 1973

Re: Indian Point Unit No. 2
Facility Operating License
DPR-26

Mr. James P. O'Reilly, Director
Regulatory Operations, Region 1
U.S. Atomic Energy Commission
631 Park Avenue
King Of Prussia, Pennsylvania 19406

In accordance with the requirements of Technical Specification 6.12.2 of Facility Operating License DPR 26, we wish to inform you of an abnormal occurrence (A.O. 3-2-14) which was identified on October 17, 1973. Prior to planned maintenance on the three pressurizer code safety valves, the set pressure of these valves was determined in order to provide further information which might be instrumental in resolving a seat leakage problem. The set pressure of one valve was found approximately 0.6% higher than the limit specified in Section 3.1 of the facility Technical Specifications. The set pressure of the remaining two valves was found approximately 1.0% higher than the limit.

During the current plant outage the pressurizer safety valves will be disassembled for inspection and repairs made to the seating surfaces to eliminate the leakage experienced. Upon completion of these repairs, the valves will be reassembled and reset to the correct value as specified in the Technical Specifications.

Mr. Anthony Fasano of your office was notified of this occurrence by Mr. John M. Makepeace by telephone on October 18, 1973.

Very truly yours,

Warren R. Coburn, Jr.
Warren R. Coburn, Jr.

8304050175 731101
PDR ADOCK 05000247
PDR
S