




ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649



TELEPHONE  
AREA CODE TIG 546-2700

Ginna Station  
February 6, 1975



Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Directorate of Regulatory Operations  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Subject: Abnormal Occurrence 75-03 - Failure of the LC Safety Injection  
Pump to Start Manually from Buss 16  
Ginna Station Docket #50-244

Dear Mr. O'Reilly:

This is to confirm my phone call to Mr. John Hannon this morning to report  
Abnormal Occurrence 75-03 at Ginna Station.

While conducting a retest of the LC Safety Injection Pump on Buss 16, the  
pump failed to start manually the first time it was tried. It was started  
again and it did start successfully. This test was part of the action  
taken in the investigation of Abnormal Occurrence 75-02 dated February 5,  
1975.

The PORC met and recommended a thorough inspection of the holding coil of  
the lockout relaying and the breaker by the Electricians. Any further action  
that is necessary will be carried out after the Electricians report back to  
PORC.

Very truly yours,

*Lee S. Lang*

Lee S. Lang  
Assistant Superintendent

LSL:fah

cc: Mr. J. F. O'Leary, NRC  
Mr. G. J. Swarthout, RG&E  
Mr. L. D. White, Jr., RG&E

1529

8304060034 750214  
PDR ADOCK 05000244  
S PDR